



report date: 2024-03-29

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	Black
Year of manufacture	-
Top speed	113 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-27
Pictures	15
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #13	2022-07-21 07:29
MOT test number	441068767322
Result	✓ Passed
Next expiry date	2023-07-30
Advice	Front Brake pad(s) wearing thin both (1.1.13 (a) (ii))

MOT #12	2021-07-26 12:49
MOT test number	885104383752
Result	✓ Passed

MOT #11	2020-07-31 12:50
MOT test number	404250994096
Result	✓ Passed
Advice	Engine oil leak
Advice	Rear brake pads worn very close to 1.5mm MOT fail limit

MOT #10	2020-07-31 09:36
MOT test number	563769372314
Result	✗ Failed
Advice	Engine oil leak
MAJOR	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Rear brake pads worn very close to 1.5mm MOT fail limit

**MOT #9**

2019-08-20 15:58

MOT test number

929872893926

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 235/50r19 (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2.5mm 235/50r19 (5.2.3 (e))

MOT #8

2019-08-20 08:12

MOT test number

927673594646

Result

✗ Failed

- MAJOR** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2.5mm 235/50r19 (5.2.3 (e))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Coolant bottle level low
- MAJOR** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- MAJOR** Reversing lamp inoperative (4.6.1 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 235/50r19 (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #7

2018-09-17 15:11

MOT test number

866863693171

Result

✓ Passed

**MOT #6** 2018-09-17 15:11**MOT test number** 351716239302**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #5** 2018-09-13 09:33**MOT test number** 603883485766**Result** ✗ Failed**MAJOR** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Both rear tyres worn, perished**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #4** 2017-09-12 11:42**MOT test number** 917083377579**Result** ✓ Passed**Advice** Rear tyres perished**MOT #3** 2017-09-12 11:42**MOT test number** 207960373904**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Rear tyres perished**Pass with rectification** Registration plate lamp not working both (1.1.C.1d)



MOT #2	2016-08-19 08:44
MOT test number	817289612088
Result	✓ Passed
Advice	Items removed from driver's view prior to test
Advice	Oil leak
Advice	Engine cover fitted.

MOT #1	2015-09-07 13:29
MOT test number	357345620087
Result	✓ Passed
Advice	No emission detected




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	LL62PXA
Plate since	2019-03-29
Current registration	LL62PXA
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-11-23
Last registration	2022-07-21
Complete history	See info



Registration #1	2012-11-23	9 mi
Registration #2	2015-09-07	10.735 mi
Registration #3	2016-08-19	17.050 mi
Registration #4	2017-09-12	26.491 mi
Registration #5	2017-09-12	26.491 mi
Registration #6	2018-09-13	35.110 mi
Registration #7	2018-09-17	35.126 mi
Registration #8	2018-09-17	35.126 mi
Registration #9	2019-09-17	35.126 mi
Registration #10	2019-09-17	35.126 mi
Registration #11	2019-09-17	35.126 mi
Registration #12	2019-09-17	35.126 mi
Registration #13	2019-09-17	35.126 mi
Registration #14	2019-09-17	35.126 mi
Registration #15	2019-09-17	35.126 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1921 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	202373K