





report date: 2024-03-29

General information

Make	CITROEN
Model	DISPATCH 1000 L1H1 ENTERPRISE P/V HDI
Colour	White
Year of manufacture	2016
Top speed	90 mph
0 - 60 mph	16.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	180 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	42.2 mpg
CO2 emission	177 g/km
CO2 label	I



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-15

Pictures 10

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2025-01-07
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	17
Total items failed	3

MOT #10		2024-01-08 13:10
MOT test	number	653430597042
Result		✓ Passed
Next expi	ry date	2025-01-07
Advice	Offside Rear Nail in tyre	
Advice	Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	

MOT #9		2024-01-08 13:10
MOT test	number	799885595108
Result		× Failed
Pass wit	h rectification Front Windscreen washer provides insufficient washer	liquid (3.5 (a))
Advice	Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Rear Nail in tyre	

CarCheck.co.uk page 3/12



report date: 2024-03-29

 MOT #8
 2022-12-19 10:23

 MOT test number
 104499386466

 Result
 ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2022-12-16 12:44

MOT test number 154486547688

Result X Failed

MAJOR Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2021-12-13 15:54

MOT test number 798819691255

Result \rightarrow Passed

MOT #5 2021-10-12 17:28

MOT test number 350046154664

Result ✓ Passed

MOT #4 2021-10-12 17:28

MOT test number 225234138806

Result X Failed

Pass with rectification Nearside Front Headlamp aim too low (4.1.2 (a))

Pass with rectification Offside Front Headlamp aim too low (4.1.2 (a))

MOT #3 2020-06-19 16:28

MOT test number 733068838567

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #2 2019-07-18 07:05

MOT test number 200202972602

MOT #1 2019-07-17 13:31

MOT test number 358441740152

Result X Failed

MAJOR Nearside Rear reflector defective or damaged by more than 50% of the reflecting surface (4.8.1 (a) (ii))

MAJOR Driver's view of the road through the swept area of the windscreen materially affected by an obstruction air freshener (3.1 (a) (ii))

MAJOR Offside Rear reflector defective or damaged by more than 50% of the reflecting surface (4.8.1 (a) (ii))

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



MOT

Expires:
7 January 2025

Tax expired: 1 February 2024

Tax status Expired at 1 February 2024

Days left 88 days too late

MOT expiry date 7 January 2025

Full MOT history See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Ow		la : -	
()\//	ner	nısı	

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r		EN
THE STATE OF THE S		

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-07-26
Last registration	2024-01-08
Complete history	See info



Registration #1	2016-07-26	22 mi
Registration #2	2019-07-17	63.815 mi
Registration #3	2019-07-18	63.887 mi
Registration #4	2020-06-19	79.792 mi
Registration #5		11.777 es
Registration #6	2021-10-12	96.091 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Additional information

Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	JBDF0089439

CarCheck.co.uk page 12/12