



report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH 1200 L2H1 ENTERPRISE HDI
Colour	White
Year of manufacture	2015
Top speed	106 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	44.1 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-12-04
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-30
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	15
Total items failed	6

MOT #8	2024-01-24 13:19
MOT test number	851534686527
Result	✓ Passed
Next expiry date	2025-01-30
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #7	2024-01-24 13:19
MOT test number	923575104707
Result	✗ Failed
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

**MOT #6** 2023-01-24 17:44**MOT test number** 462931459227**Result** ✓ Passed**Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**MOT #5** 2023-01-24 14:07**MOT test number** 836249106702**Result** ✗ Failed**Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #4** 2022-01-31 12:59**MOT test number** 952931805105**Result** ✓ Passed**MOT #3** 2020-12-09 12:53**MOT test number** 393303781223**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #2	2019-11-30 10:31
MOT test number	714192281225
Result	✓ Passed
MOT #1	2018-12-14 11:12
MOT test number	212314877351
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
30 January 2025

Tax status		Valid until 1 February
Days left		278
MOT expiry date		30 January 2025
Full MOT history		See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	ST15VDC
Plate since	2019-09-28
Current registration	ST15VDC
Plate since	2019-09-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-07-13
Last registration	2024-01-24
Complete history	See info



Registration #1	2015-07-13	19 mi
Registration #2	2018-12-14	58.049 mi
Registration #3	2019-11-30	99.047 mi
Registration #4	2020-12-09	134.215 mi
Registration #5	2021-01-20	151.277 mi
Registration #6	2021-03-20	161.277 mi
Registration #7	2021-05-20	171.277 mi
Registration #8	2021-07-20	181.277 mi
Registration #9	2021-09-20	191.277 mi
Registration #10	2021-11-20	201.277 mi

More info >



Dimensions & weight

Width	1895 mm
Height	1942 mm
Length	5135 mm
Kerb weight	1732 kg
Max. allowed weight	2932 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	DYZG4158506