



Mercedes-Benz

C7GKW

report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK280 SPORT
Colour	Black
Year of manufacture	2007
Top speed	150 mph
0 - 60 mph	7.8 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	228 BHP
Max. torque	300 Nm at 3.000 rpm
Engine capacity	2.997 cc
Cylinders	6
Fuel type	Petrol
Consumption city	20.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	29.4 mpg
CO2 emission	229 g/km
CO2 label	L





Internet history

Entry 1

Date	2022-01-07
Pictures	13
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-16
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	52
Total items failed	8

MOT #19	2024-04-17 13:05
MOT test number	499053856582
Result	✓ Passed
Next expiry date	2025-04-16
Advice	Rear Brake pipe corroded, covered in grease or other material both sides (1.1.11 (c))

MOT #18	2024-04-15 15:15
MOT test number	476891003640
Result	✗ Failed
Fail	Nearside Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))
Fail	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Rear Brake pipe corroded, covered in grease or other material both sides (1.1.11 (c))

**MOT #17**

2023-01-24 15:38

MOT test number

433539335552

Result

✓ Passed

- Advice** Offside Front wing has damage
- Advice** Front Brake pipe corroded, covered in grease or other material both (1.1.11 (c))
- Advice** Engine covers and undertrays fitted
- Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
- Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material both (1.1.11 (c))
- Advice** Rear axle and suspension components corroded
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #16

2022-01-21 10:10

MOT test number

355694341837

Result

✓ Passed

MOT #15

2021-04-23 15:31

MOT test number

612794030107

Result

✓ Passed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Undertrays fitted
- Advice** Front Service brake fluctuating, but not excessively both sides (1.2.1 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #14** 2021-04-21 08:03**MOT test number** 215085169164**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Undertrays fitted**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Service brake fluctuating, but not excessively both sides (1.2.1 (e))**MOT #13** 2020-05-19 08:42**MOT test number** 485993667865**Result** ✓ Passed**MOT #12** 2019-04-04 08:22**MOT test number** 140361589784**Result** ✓ Passed**Advice** Rear Brake pipe corroded, covered in grease or other material both sides (1.1.11 (c))**Advice** Plastic undertrays fitted**MOT #11** 2018-05-09 16:11**MOT test number** 658034736624**Result** ✓ Passed

**MOT #10** 2018-05-09 08:47**MOT test number** 829849683959**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake discs corroded on inner faces**Fail** Front brake application uneven (3.7.B.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2017-05-02 07:46**MOT test number** 704398124864**Result** ✓ Passed**MOT #8** 2016-05-10 07:36**MOT test number** 138798131423**Result** ✓ Passed**MOT #7** 2015-05-20 08:49**MOT test number** 537890545161**Result** ✓ Passed

**MOT #6** 2014-05-27 13:00**MOT test number** 808007444160**Result** ✓ Passed**Notice** Unable to check full length of fuel/brake pipes due to covers fitted**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)**Notice** Under-trays fitted obscuring some underside components**Notice** Nearside front wheel bearing slight freeplay**MOT #5** 2013-05-31 10:10**MOT test number** 246831053174**Result** ✓ Passed**Notice** Nearside front tyre slight wear on outter edge**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2012-06-06 16:46**MOT test number** 165148952117**Result** ✓ Passed**Advice** Nearside front brake juddering slightly (3.7.A.2b)**Notice** Unable to check full length of brake/fuel pipes due to covers fitted**Notice** Both front to rear metal brake pipes slight corrosion**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside front brake juddering slightly (3.7.A.2b)**Notice** Front brake discs slight corrosion and wear

**MOT #3**

2012-06-01 10:35

MOT test number

375293052176

Result**✗ Failed**

- Notice** Front brake discs slight corrosion and wear
- Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice** Offside front brake juddering slightly (3.7.A.2b)
- Notice** Unable to check full length of brake/fuel pipes due to covers fitted
- Notice** Both front to rear metal brake pipes slight corrosion
- Advice** Nearside front brake juddering slightly (3.7.A.2b)
- Notice** Engine covers fitted obscuring some components in the engine bay

MOT #2

2011-05-23 15:49

MOT test number

856353041180

Result**✓ Passed**

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Front brake discs slight wear
- Notice** Nearside front tyre wearing inner edge
- Advice** Offside Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Unable to check full length of fuel/brake pipes due to covers fitted
- Notice** Nearside front tyre inner wall slight damage not deep enough to reach wall or plies
- Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)

MOT #1

2010-06-02 13:25

MOT test number

762283350187

Result**✓ Passed**



Tax & MOT check

X

Untaxed

Tax expired:
1 April 2024

✓

MOT

Expires:
16 April 2025

Tax status	Expired at 1 April 2024
Days left	28 days too late
MOT expiry date	16 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-28
Current registration	 XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-06-20
Last registration	2024-04-17
Complete history	See info



Registration #1	2007-06-20	14 mi
Registration #2	2010-06-02	22.019 mi
Registration #3	2011-05-23	29.357 mi
Registration #4	2012-06-01	36.070 mi
Registration #5	2012-06-06	36.073 mi
Registration #6	2013-05-31	41.996 mi
Registration #7	2014-05-27	50.384 mi
Registration #8	2015-05-20	57.901 mi
Registration #9	2016-05-10	68.265 mi
Registration #10	2017-05-02	71.825 mi
Registration #11	2018-05-09	76.380 mi
Registration #12	2019-05-09	81.935 mi
Registration #13	2020-05-09	87.490 mi
Registration #14	2021-05-09	93.045 mi
Registration #15	2022-05-09	98.600 mi
Registration #16	2023-05-09	104.155 mi
Registration #17	2024-04-17	109.710 mi
Registration #18		
Registration #19		
Registration #20		
Registration #21		

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2690 mm
Kerb weight	1705 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27294030589725