





report date: 2024-03-28

General information

Make	MINI
Model	MINI COOPER S
Colour	Grey
Year of manufacture	2010
Top speed	142 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	136 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 2


Date 2021-06-14

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



RV60TKU
report date: 2024-03-28

MOT history

MOT expiry date	2024-05-20
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	15
Total items failed	4

MOT #12		2023-05-17 11:01
MOT test	number	223992740505
Result		✓ Passed
Next expi	ry date	2024-05-20
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2.6mm (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2.7mm (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 2.7mm (5.2.3 (e))	

MOT #11		2022-05-21 11:58
MOT test number		730368889639
Result		✓ Passed
Advice Offside R	ear Tyre slightly damaged/cracking or perishing	g (5.2.3 (d) (ii))
Minor Offside Re	ear Stop lamp(s) with a multiple light source up	to 1/2 not functioning (4.3.1 (a) (i))

MOT #10	2021-05-10 14:41
MOT test number	617259343796
Result	✓ Passed
MOT #9	2020-11-25 11:39
MOT test number	445243604596
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #8

MOT test number

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)

Advice Nearside Front Road wheel slightly damaged (4.2.A.1a)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #6 2018-02-23 18:11 **MOT** test number 981591262999 Result × Failed Nearside Front Road wheel slightly damaged (4.2.A.1a) **Advice** Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) **Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f) Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d) **Advice** Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1) Pass with rectification Offside Rear Direction indicator incorrect colour (1.4.A.2f)

 MOT #5
 2017-02-20 16:25

 MOT test number
 883239127559

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #4 2017-02-20 13:14

MOT test number 562689170992

Result × Failed

Advice Offside Front wiper not cleaning screen properly

Advice Front pads low

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #3 2015-12-04 11:06

MOT test number 181428984229

Result ✓ Passed

MOT #2 2014-12-09 08:56

MOT test number 959473344378

Result ✓ Passed

Notice Slight play in nearside steering arm

MOT #1 2013-12-13 14:46

MOT test number 866237843360

Result
✓ Passed

CarCheck.co.uk page 5/12



RV60TKU
report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	20 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

\sim		
Owner	hictory	7
OWITCE	1113601	1

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report		e?

	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		
Current registration	UK NEZ	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



RV60TKU report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-12-17
Last registration	2023-05-17
Complete history	See info



Registration #1	2010-12-17	22 mi
Registration #2	2013-12-13	32.924 mi
Registration #3	2014-12-09	38.319 mi
Registration #4	2015-12-04	45.004 mi
Registration #5	2017-02-20	49.894 mi
Registration #6	2017-02-20	49.894 mi
Registration #7	2018-02-23	55.620 mi
Registration #8		11.177 es
Registration #9		11.777 es
Registration #10		11.177 es
Registration #11		11.777 es
Registration #12		11.177 es
Registration #13		11.777 es

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3714 mm
Wheel base	2467 mm
Kerb weight	1130 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2
Engine number A7111774