



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX35 CRDI PREMIUM
Colour	Black
Year of manufacture	2014
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	147 g/km
CO2 label	F






Internet history

Entry 3

Date	2021-08-06
Pictures	24
Listing price	View report



source: [autotrader.co.uk](#)

Entry 2


Date	2021-07-20
Pictures	1
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-19
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-11-01
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	7
Total items failed	9

MOT #10	2023-11-01 10:54
MOT test number	339760970240
Result	✓ Passed
Next expiry date	2024-11-01
Advice	Tyre slightly damaged/cracking or perishing BOTH REARS (5.2.3 (d) (ii))

MOT #9	2022-11-02 13:43
MOT test number	163104557107
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing Badly perished and close to limit (5.2.3 (d) (ii))
Minor	Window damaged but not adversely affecting driver's view Chip in screen (3.2 (a) (i))

MOT #8	2022-11-01 14:24
MOT test number	933278899237
Result	✗ Failed
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Nearside Rear Service brake imbalanced across an axle (1.2.1 (b) (i))
Minor	Window damaged but not adversely affecting driver's view Chip in screen (3.2 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing Badly perished and close to limit (5.2.3 (d) (ii))
Fail	Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

**MOT #7** 2021-10-21 10:11**MOT test number** 496352568570**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6** 2020-11-02 13:17**MOT test number** 382340025869**Result** ✓ Passed**MOT #5** 2020-10-20 07:32**MOT test number** 586376806274**Result** ✗ Failed**Fail** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Fail** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #4** 2019-09-11 11:06**MOT test number** 777234466495**Result** ✓ Passed**MOT #3** 2018-09-28 14:55**MOT test number** 145451069407**Result** ✓ Passed**Minor** Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



MOT #2	2018-09-28 09:03
MOT test number	849923190476
Result	✗ Failed
Fail	Offside Headlamp aim too low (4.1.2 (a))
Fail	Nearside Headlamp aim too low (4.1.2 (a))
Fail	Headlamp levelling device inoperative (4.1.5 (a))

MOT #1	2017-09-22 09:27
MOT test number	560771164492
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
1 November 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	1 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-09-29
Last registration	2023-11-01
Complete history	See info



Registration #1	2014-09-29	19 mi
Registration #2	2017-09-22	41.611 mi
Registration #3	2018-09-28	58.651 mi
Registration #4	2018-09-28	58.654 mi
Registration #5	2019-09-11	64.192 mi
Registration #6	2020-10-20	71.089 mi
Registration #7	2020-11-02	71.098 mi
Registration #8	2020-11-02	71.098 mi
Registration #9	2020-11-02	71.098 mi
Registration #10	2020-11-02	71.098 mi
Registration #11	2020-11-02	71.098 mi
Registration #12	2020-11-02	71.098 mi
Registration #13	2020-11-02	71.098 mi
Registration #14	2020-11-02	71.098 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FDDZ222307