





report date: 2024-03-28

General information

Make	VOLVO
Model	V60 D2 CROSS COUNTRY PRO
Colour	Blue
Year of manufacture	2018
Top speed	118 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	120 BHP
Max. torque	280 Nm at 2.250 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/11



SH180UG

report date: 2024-03-28

Internet history

Entry 6

Date 2021-10-02

Pictures 44

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 5

Date	2021-10-02
Pictures	0
Listing price	View report

source: heycar.co.uk

Entry 4

Date 2021-08-13

Pictures 44

Listing price <u>View report</u>









source: heycar.co.uk

Entry 3

Date	2021-08-08
Pictures	5
Listing price	View report

CarCheck.co.uk page 2/11









source: autoonline.co.uk

Entry 2

Date 2021-07-23

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-07-22
Pictures	0
Listing price	<u>View report</u>

source: autotrader.co.uk



SH18OUG report date: 2024-03-28

MOT history

MOT expiry date	2024-06-12
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	14
Total items failed	0

MOT #5		2023-06-09 10:52
MOT test	number	130065178520
Result		✓ Passed
Next expi	ry date	2024-06-12
Advice	Oil leak, but not excessive leaking engine oil (8.4.1 (a) (i))	
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge tread area	wearing bald (5.2.3 (e))
Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge tread area wearing bald and down to 3mm in tread area (5.2.3 (e))		

MOT #4	2022-06-09 08:13
MOT test number	545671016216
Result	✓ Passed
Advice Emissions too clean to test	

MOT #3	2022-06-08 10:01
MOT test number	986747884546
Result	X Failed
DANGEROUS Brake pad(s) less than 1.5 mm thick front and rear (1.1.13 (a) (ii))	
MAJOR Brake disc significantly and obviously worn front and rear (1.1.14 (a) (i))	
DANGEROUS Front Tyre tread depth below requirements of 1.6mm both (5.2.3 (e))	
Advice Emissions too clean to test	

CarCheck.co.uk page 3/11



(b) (i))

SH18OUG

report date: 2024-03-28

MOT #2 2021-05-28 09:48

MOT test number 965878466926

Result ✓ Passed

Advice Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing Arm Bushes (5.3.4 (a) (i))

MOT #1 2021-05-27 12:05

MOT test number 398396069234

Result X Failed

Advice Clutch pedal anti-slip provision missing

MAJOR Brake pedal anti-slip provision missing (1.1.2 (c))

Advice Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing Arm Bushes (5.3.4 (a) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

MAJOR Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

CarCheck.co.uk page 4/11



SH180UG

report date: 2024-03-28

Tax & MOT check





Tax expired: 21 July 2023

Tax status Expired at 21 July 2023

Days left 284 days too late

MOT expiry date 12 June 2024

Expires: 12 June 2024

Full MOT history See MOT history

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

SH18OUG

report date: 2024-03-28

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

See in this check if this VOLVO had different number plates.

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2018-06-13
Last registration	2023-06-09
Complete history	See info



Registration #1	2018-06-13	18 mi
Registration #2	2021-05-27	46.125 mi
Registration #3	2021-05-28	46.125 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		T1.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	2041 mm
Height	1470 mm
Length	4370 mm
Wheel base	2646 mm
Kerb weight	1450 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1