





report date: 2024-03-29

#### General information

Make	FORD
Model	TRANSIT 270 LIMITED LR P/V
Colour	White
Year of manufacture	2014
Top speed	98 mph
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	92 kW / 125 HP / 123 BHP
Max. torque	330 Nm at 1.500 rpm
<b>Engine capacity</b>	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	40.4 mpg
CO2 emission	186 g/km
CO2 label	1



CarCheck.co.uk page 1/12



### Internet history

#### Entry 1

Date	2021-10-19	
Pictures	1	
Listing price	View report	



source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-01-11
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	13
Total items failed	3

MOT #10		2024-01-12 15:25
MOT test	t number	710281213555
Result		<b>✓</b> Passed
Next exp	piry date	2025-01-11
<b>Advice</b> Rear busi	Offside Front Lower Suspension arm pin or bush worn but not resulting in exc h. (5.3.4 (a) (i))	cessive movement
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (	a) (ii))
Advice	Rear exhaust slight corrosion.	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a	a) (ii))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deterior	ated (6.1.7 (g) (i))

MOT #9	2022-12-21 15:34
MOT test number	966871528671
Result	✓ Passed
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorat (6.1.7 (g) (i))	ed Leaking grease.
Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excess Rear bush. (5.3.4 (a) (i))	ssive movement
Advice Nearside Front Outer Tyre slightly damaged/cracking or perishing Sidewall. (5.2)	2.3 (d) (ii))
Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))

CarCheck.co.uk page 3/12



**VE64RZT** 

report date: 2024-03-29

MOT #8 2022-01-07 14:12

**MOT test number** 704913458188

**Result** 
✓ Passed

MOT #7 2022-01-07 14:12

**MOT test number** 136546541395

Result × Failed

**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #6 2021-01-04 14:25

**MOT test number** 234803213563

**Result** ✓ Passed

MOT #5 2019-12-23 12:29

**MOT test number** 689288181706

Result \rightarrow Passed

MOT #4 2019-12-23 09:22

**MOT test number** 234616659817

**Result** X Failed

**Fail** Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #3 2019-01-03 14:33

MOT test number 129228164320

Result 

Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))

CarCheck.co.uk page 4/12



**VE64RZT** 

report date: 2024-03-29

MOT #2	2017-12-08 17:03
MOT test number	738679641230
Result	✓ Passed
MOT #1	2017-12-08 12:57
MOT test number	538040042196
Result	<b>×</b> Failed
Fail Offside Headlamp insecure (1.7.3)	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	11 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



**VE64RZT** 

report date: 2024-03-29

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

*		
For how long did the current and previous owner(s) have this FORD? How many owners defect it in the premium report and see all owner registrations. Download the full report is		ave?
********		
***************************************		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-12-12
Last registration	2024-01-12
Complete history	See info



Registration #1	2014-12-12	19 mi
Registration #2	2017-12-08	31.615 mi
Registration #3	2017-12-08	31.615 mi
Registration #4	2019-01-03	39.100 mi
Registration #5	2019-12-23	47.664 mi
Registration #6	2019-12-23	47.665 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		n

More info >

CarCheck.co.uk page 11/12



### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	84%
Children	90%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



## Dimensions & weight

Width	2272 mm
Height	2020 mm
Length	4972 mm
Wheel base	2933 mm
Kerb weight	1817 kg
Max. allowed weight	2700 kg

# Additional information

Fuel tank capacity	80 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	3 pa	ge 12/12

Number of axles 2

**Engine number** EP67550