





report date: 2024-03-28

# General information

Make	VOLKSWAGEN
Model	CC GT TDI BLUEMOTION TECHNOLOGY DSG
Colour	Black
Year of manufacture	2015
Top speed	137 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed Semi Auto

# Engine & fuel consumption

Power	175 BHP
Max. torque	380 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	133 g/km
CO2 label	E



CarCheck.co.uk page 1/10



# Internet history


# Entry 1

Date 2021-10-10

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/10



MOT history

MOT expiry date	2025-03-31
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	10
Total items failed	0

MOT #7	2024-04-01 14:28
MOT test number	195473837544
Result	<b>✓</b> Passed
Next expiry date	2025-03-31

	01 #0	20	24 01 13 10.20
М	OT test	number	716386632284
R	esult		× Failed
	MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
	MAJOR	Windscreen washer not working (3.5 (a))	
	MAJOR	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (kg)	o) (ii))

MOT #5	2	022-03-21 10:56
MOT test	number	384828787401
Result		✓ Passed
Advice Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))		
Advice	Spare tyre defective	
Advice	Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (	o) (i))

CarCheck.co.uk page 3/10



MOT #4 2021-03-21 17:31

**MOT test number** 939271375998

**Result** ✓ Passed

Advice Emission too clean to detect

MOT #3 2020-02-06 12:00

**MOT test number** 218143617485

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement REAR BUSH (5.3.4 (a) (i))

MOT #2 2019-03-07 16:38

**MOT test number** 922931317931

**Result** 
✓ Passed

MOT #1 2018-06-04 14:32

**MOT test number** 491845080476

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date
Category

**Type** 

Damage 2

**Date** 

Category

**Type** 



#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
***************************************	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	AIR AIR
Plate since	
	More info >

CarCheck.co.uk page 7/10



#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combact info	

**Contact info** 

More info >

CarCheck.co.uk page 8/10



# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-06-30
Last registration	2024-04-01
Complete history	See info



Registration #1	2015-06-30	19 mi
Registration #2	2018-06-04	60.247 mi
Registration #3	2019-03-07	73.650 mi
Registration #4	2020-02-06	82.414 mi
Registration #5	2021-03-21	91.122 mi
Registration #6		71.777 66
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 9/10



# Car features

50225	Air conditioning
50295	
60482	
60501	
0566	
0567	
60569	

# Dimensions & weight

Width	2090 mm
Height	1421 mm
Length	4902 mm
Wheel base	2710 mm
Kerb weight	1581 kg
Max. allowed weight	2110 kg

# Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	CFGC620848

CarCheck.co.uk page 10/10