



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF GTI DSG
Colour	Silver
Year of manufacture	2009
Top speed	148 mph
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	210 BHP
Max. torque	280 Nm at 1.700 rpm
Engine capacity	2.000 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.3 mpg
Consumption extra urban	47.9 mpg
Consumption combined	38.2 mpg
CO2 emission	173 g/km
CO2 label	H






Internet history

Entry 2



Date	2021-06-27
Pictures	9
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-13
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-03-28
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	21
Total items failed	2

MOT #15	2024-03-11 09:20
MOT test number	811239121699
Result	✓ Passed
Next expiry date	2025-03-28

MOT #14	2023-03-29 07:02
MOT test number	305236479120
Result	✓ Passed
Advice	Brake disc worn, pitted or scored, but not seriously weakened front and rear (1.1.14 (a) (ii))

MOT #13	2022-03-24 15:41
MOT test number	581185385440
Result	✓ Passed
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12	2021-03-25 11:00
MOT test number	426420033893
Result	✓ Passed

**MOT #11** 2020-04-27 13:13**MOT test number** 260917155462**Result** ✓ Passed**MOT #10** 2019-08-14 10:00**MOT test number** 331796107276**Result** ✓ Passed**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #9** 2019-08-13 15:00**MOT test number** 340645228978**Result** ✗ Failed**MAJOR** Offside Side repeater not working (4.4.1 (a) (ii))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Items removed from driver's view prior to test**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #8** 2018-08-22 10:57**MOT test number** 768563884038**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Minor** Windscreen damaged but not adversely affecting driver's view stone chip (3.2 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Items removed from driver's view prior to test

**MOT #7** 2017-08-21 08:49**MOT test number** 324673927094**Result** ✓ Passed**MOT #6** 2016-08-23 12:34**MOT test number** 628634359916**Result** ✓ Passed**MOT #5** 2015-09-04 14:32**MOT test number** 325007445253**Result** ✓ Passed**MOT #4** 2014-09-03 12:19**MOT test number** 458676044268**Result** ✓ Passed**MOT #3** 2014-09-03 12:19**MOT test number** 696696044271**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2013-09-03 12:41**MOT test number** 425156943209**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Tyre worn close to the legal limit (4.1.E.1)



MOT #1 2012-09-04 14:05

MOT test number 349458742417

Result ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Front screen lightly marked.
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
28 March 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	28 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 BF59KZV
Plate since	2019-06-29
Current registration	 BF59KZV
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-03
Last registration	2024-03-11
Complete history	See info



Registration #1	2009-09-03	18 mi
Registration #2	2012-09-04	22.734 mi
Registration #3	2013-09-03	27.284 mi
Registration #4	2014-09-03	31.887 mi
Registration #5	2015-09-04	35.751 mi
Registration #6	2016-08-23	39.159 mi
Registration #7	2017-08-21	42.623 mi
Registration #8	2018-08-22	46.929 mi
Registration #9	2019-08-13	50.850 mi
Registration #10	2020-08-13	54.771 mi
Registration #11	2021-08-13	58.692 mi
Registration #12	2022-08-13	62.613 mi
Registration #13	2023-08-13	66.534 mi
Registration #14	2024-03-11	70.455 mi
Registration #15	2024-03-11	74.376 mi
Registration #16	2024-03-11	78.297 mi
Registration #17	2024-03-11	82.218 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2048 mm
Height	1479 mm
Length	4213 mm
Wheel base	2575 mm
Kerb weight	1339 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CCZ 025749