





report date: 2024-03-29

General information

Make	KIA
Model	CEED GT-LINE ISG
Colour	Red
Year of manufacture	2017
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	171 Nm at 4.000 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	45.6 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.7 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/11



Internet history

Е,	2+	PA.	, 7)

Date	2021-10-01
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Lifti y 1	
Date	2021-10-01
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-10-26
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	12
Total items failed	3

MOT #6	2023-10-03 07:44
MOT test number	996411373489
Result	✓ Passed
Next expiry date	2024-10-26
Advice Tyre pressure warning light on.	

MOT #5		2023-10-03 07:44
MOT test number		407777411095
Result		× Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice Tyre pressure w	arning light on.	

MOT #4		2022-10-27 15:02
MOT test	number	490074482943
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



MOT #3 2022-10-26 08:54

MOT test number 893299155162

Result X Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Offside Side repeater with a multiple light source more than 1/2 not functioning (4.4.1 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #2 2021-10-14 09:29

MOT test number 519820001062

Result
✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1 2020-10-27 08:22

MOT test number 736743358909

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	26 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>l</u>	

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Current registration	NK NIE
Plate since	mm.m.m
Current registration	UK SIP
Plate since	Jn
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-09-01
Last registration	2023-10-03
Complete history	See info



Registration #1	2017-09-01	23 mi
Registration #2	2020-10-27	22.028 mi
Registration #3		11.177 es
Registration #4		77.777 46
Registration #5	2021-10-14	33.098 mi
Registration #6		11.777 au
Registration #7		11,177 esi
Registration #7 Registration #8		11.777 ea

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	88%
Pedestrian	61%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1470 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1402 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

Engine number G3LCHP080123