





report date: 2024-03-28

General information

Make	RENAULT
Model	TRAFIC SL27 DEBUT DCI S/R P/V
Colour	White
Year of manufacture	2012
Top speed	93 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	260 Nm at 1.500 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	43.5 mpg
Consumption combined	37.7 mpg



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

_		•		_	-
-	n	т	rv	,	

Elitiy 1	
Date	2021-08-11
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/12



HN12GVW report date: 2024-03-28

MOT history

MOT expiry date	2024-11-02
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	10
Total items failed	8

MOT #10		2023-11-03 12:33
MOT test r	number	119217555840
Result		✓ Passed
Next expir	y date	2024-11-02
Advice	Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	
Advice	Nearside Front Steering linkage ball joint has slight play (2.1.3 (b) (i))	
Advice	Nearside Play in steering rack inner joint(s)	

MOT #9	2022-11-02 17:28
MOT test	number 653160287800
Result	✓ Passed
Advice	Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #8	2022-10-18 15:10
MOT test number	113469941765
Result	× Failed
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Nearside Front Headlamp aim too high (4.1.2 (a))	
Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, n ingress of dirt (6.1.7 (g) (ii))	o longer prevents the
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Offside Front Anti-roll bar pin or bush worn but not resulting in excessive mo	ovement (5.3.4 (a) (i))
Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	
Fail Offside Rear Direction indicator not working (4.4.1 (a) (ii))	
Fail Offside Front Headlamp aim too high (4.1.2 (a))	
Fail Offside Rear Wheel bearing has excessive play (5.1.3 (a) (i))	
Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))	

MOT #7	2021-07-20 13:22
MOT test number	885141923810
Result	✓ Passed
MOT #6	2020-07-01 09:09
MOT test number	602667644401
Result	✓ Passed
MOT #5	2019-06-18 09:15
MOT test number	149587931506
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #4 2018-06-13 16:03

MOT test number 917459158672

Result ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))

MOT #3 2017-05-31 11:21

MOT test number 275732135788

Result \(\sqrt{Passed} \)

MOT #2 2016-06-14 08:01

MOT test number 449133339807

Result

Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #1 2015-05-14 11:05

MOT test number 125104435195


Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Days left 187

MOT expiry date 2 November 2024

Full MOT history See MOT history

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



faste since

HN12GVW

report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this RENAULT had different number plates. ober of plates

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-06-11
Last registration	2023-11-03
Complete history	See info



2012-06-11	22 mi
2015-05-14	79.445 mi
2016-06-14	81.204 mi
2017-05-31	84.732 mi
2018-06-13	87.201 mi
2019-06-18	89.774 mi
	11.777 es
	111.7777 ess
	11.177 es
	11.777 es
	11.117 es
	2015-05-14 2016-06-14 2017-05-31 2018-06-13

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Additional information

-	
Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	C021890

CarCheck.co.uk page 12/12