





report date: 2024-03-28

General information

Make	KIA
Model	VENGA 3 ISG
Colour	Red
Year of manufacture	2016
Top speed	114 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP	
Max. torque	156 Nm at 4.200 rpm	
Engine capacity	1.591 cc	
Cylinders	4	
Fuel type	Petrol	
Consumption city	39.8 mpg	
Consumption extra urban	54.3 mpg	
Consumption combined	47.9 mpg	
CO2 emission	139 g/km	
CO2 label	E	



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-08-20

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT expiry date	2024-07-22
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	9
Total items failed	3

MOT #6		2023-07-05 09:33
MOT test	number	679082690137
Result		✓ Passed
Next expi	ry date	2024-07-22
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))		
Advice	Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	

MOT #5		2022-07-15 10:59
MOT test	number	902137324207
Result		✓ Passed
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		(1.1.14 (a) (ii))
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4	2021-07-19 11:44
MOT test number	274734744437
Result	✓ Passed
Advice Nearside Front Nail in tyre	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #3 2020-07-23 15:59

MOT test number 772226433141

Result ✓ Passed

MOT #2 2020-07-23 10:27

MOT test number 948433298831

Result X Failed

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Rear Nail in tyre

Fail Offside Front Tyre has ply or cords exposed on tread area (5.2.3 (d) (ii))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Rear Nail in tyre

MOT #1 2019-07-12 14:49

MOT test number 579824590968

CarCheck.co.uk page 4/11



SK66EHX report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	22 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



faste since

SK66EHX

report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this KIA had different number plates. about of pliates

CarCheck.co.uk page 8/11



SK66EHX report date: 2024-03-28

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-09-16
Last registration	2023-07-05
Complete history	See info



Registration #1	2016-09-16	22 mi
Registration #2	2019-07-12	10.424 mi
Registration #3	2020-07-23	12.020 mi
Registration #4	2020-07-23	12.021 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		

More info >

page 10/11 CarCheck.co.uk



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4075 mm
Wheel base	2615 mm
Kerb weight	1355 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1:

Number of axles 2

Engine number G4FCGZ646797