





report date: 2024-03-28

General information

Make	FORD
Model	RANGER DCB 4X4
Colour	Silver
Year of manufacture	2009
Gearbox	5 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	330 Nm at 1.800 rpm
Engine capacity	2.500 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/16



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-30

Pictures 24

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/16



EOO9THV report date: 2024-03-28

MOT history

MOT expiry date	2025-01-21
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	48
Total items failed	12

MOT #17		2024-01-22 15:33
MOT test	number	797485040598
Result		✓ Passed
Next expi	ry date	2025-01-21
Advice	Rear Vehicle structure is corroded but structural rigidity is not significan	ntly reduced (6.1.1 (c) (i))
Advice	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (iii))
Advice	Front Vehicle structure is corroded but structural rigidity is not significant	ntly reduced (6.1.1 (c) (i))

MOT #16		2023-01-10 13:59
MOT test	number	978000491769
Result		✓ Passed
Advice	Brake pipe corroded, covered in grease or other material Front to rear (1.1.11	(c))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Front panel corroded	
Advice	One v belt missing	
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Nearside Front Steering idle arm has small play	

CarCheck.co.uk page 3/16



report date: 2024-03-28

MOT #15 2021-12-08 09:24

MOT test number 810518612048

Result ✓ Passed **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) **Advice** V belt missing **Advice** Central Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice Advice** Steering box has slight free play detected at steering wheel (2.3 (a) (i)) Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) **Advice** Nearside Rear Light lens damaged Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

CarCheck.co.uk page 4/16



report date: 2024-03-28

MOT #14 2021-12-06 14:40 **MOT** test number 406716679370 Result × Failed **Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Rear Stop lamp(s) missing (4.3.1 (a) (ii)) Fail Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) V belt missing **Advice Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Central Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) Nearside Rear Light lens damaged Advice

MOT #13 2020-11-25 17:57

MOT test number 360857907823

Result
✓ Passed

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Steering box has slight free play detected at steering wheel (2.3 (a) (i))

Advice Nearside Rear lens cracked

Advice

CarCheck.co.uk page 5/16



report date: 2024-03-28

MOT #12 2019-09-20 16:59

MOT test number 144484341434

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #11 2018-09-08 09:01

MOT test number 842908290996

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #10 2017-09-29 14:14

MOT test number 824261313440

Result ✓ Passed

Advice Front Brake pad(s) wearing thin 80% worn aprox. (3.5.1g)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #9 2017-09-28 11:39

MOT test number 388271302093

Result × Failed

Advice Front Brake pad(s) wearing thin 80% worn aprox. (3.5.1g)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Rear fog lamp not working (1.3.2b)

MOT #8 2016-06-21 11:58

MOT test number 647941160763

Result ✓ Passed

CarCheck.co.uk page 6/16



MOT test number

EO09THV

report date: 2024-03-28

985410694022

MOT #7

MOT test number

2016-06-20 09:51

Result

Failed

Fail Rear fog lamp not working (1.3.2b)

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

 MOT #6
 2015-04-17 12:35

 MOT test number
 495977105126

Result

Passed

MOT #5 2014-03-31 15:28

Post II

Result ✓ Passed

CarCheck.co.uk page 7/16



report date: 2024-03-28

MOT #4 2014-03-27 16:53

MOT test number 135896284099

Result X Failed

Notice Engine covers fitted obscuring some components in the engine bay

Fail Offside Front Headlamp not working on main beam (1.7.5a)

Fail Offside Rear fog lamp not working (1.3.2b)

Notice Vehicle's internal headlight adjuster altered to recheck lights

Fail Shock absorber has a serious fluid leak (2.7.3)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Notice Oil leak

Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)

Notice Under-trays fitted obscuring some underside components

Fail Nearside Front Steering pivot point has excessive play (2.2.B.1g)

Notice N/s/f tyre badly worn on outer edge

MOT #3 2013-03-16 15:40

MOT test number 556305773018

Result

✓ Passed

MOT #2 2012-03-28 13:59

MOT test number 357208382031

CarCheck.co.uk page 8/16



report date: 2024-03-28

MOT test number

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 9/16



report date: 2024-03-28

See MOT history

Tax & MOT check

Full MOT history



CarCheck.co.uk page 10/16



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 12/16



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report if	
THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 13/16



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 14/16



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-03-27
Last registration	2024-01-22
Complete history	See info



Registration #1	2009-03-27	15 mi
Registration #2	2012-03-27	64.180 mi
Registration #3	2012-03-28	64.192 mi
Registration #4	2013-03-16	86.526 mi
Registration #5	2014-03-27	110.848 mi
Registration #6	2014-03-31	111.026 mi
Registration #7	2015-04-17	129.110 mi
Registration #8	2016-06-20	151.599 mi
Registration #9	2016-06-21	151.599 mi
Registration #10	2017-09-28	173.838 mi
Registration #11		77.777 46
Registration #12		71.777 es
Registration #13		77.777 46
Registration #14		77.777 46
Registration #15		77.777 46
Registration #16		77.777 46
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		D.777 es

More info >

CarCheck.co.uk page 15/16



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	******
Video	see crash video



Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	113188

CarCheck.co.uk page 16/16