





report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Silver
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	436 Nm at 2.500 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	178 g/km
CO2 label	I



CarCheck.co.uk page 1/12



Internet history

Entry 3

Date 2021-07-29

Pictures 10

Listing price <u>View report</u>










source: autoonline.co.uk

Entry 2

Date 2021-07-23

Pictures 27

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date 2021-07-16

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-02-10
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	12
Total items failed	2

MOT #11		2024-02-02 17:01
MOT test	number	580643532938
Result		✓ Passed
Next expi	ry date	2025-02-10
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Advice Offside Rear Tyre worn close to legal limit/worn on edge Wearing on shoulders. (5.2.3 (e))	
Advice	Advice Tyre slightly damaged/cracking or perishing All tyres cracking in tread due to age. (5.2.3 (d) (ii))	
Advice	Advice Front Tyre worn close to legal limit/worn on edge BOTH tyres wearing on inner edge. (5.2.3 (e))	
Advice (1.1.14 (a)	Rear Brake disc worn, pitted or scored, but not seriously weakened Both (ii))	worn and offside scored.

CarCheck.co.uk page 3/12



MOT #10 2024-02-02 13:36

MOT test number 930823515774

Result X Failed

Advice Tyre slightly damaged/cracking or perishing All tyres cracking in tread due to age. (5.2.3 (d) (ii))

Minor Windscreen wiper blade defective BOTH. (3.4 (b) (i))

Advice Front Tyre worn close to legal limit/worn on edge BOTH tyres wearing on inner edge. (5.2.3 (e))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both worn and offside scored.

(1.1.14 (a) (ii))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge Wearing on shoulders. (5.2.3 (e))

MOT #9 2023-02-09 13:35

MOT test number 332705335115

Result \rightarrow Passed

MOT #8 2023-02-09 08:40

MOT test number 440017117535

Result ★ Failed

Fail Brake pad(s) less than 1.5 mm thick NSF/OSF/NSR/OSR/ (1.1.13 (a) (ii))

MOT #7 2022-02-09 15:36

MOT test number 624201713886

MOT #6 2021-02-11 14:25

MOT test number 963925099383

Result
✓ Passed

CarCheck.co.uk page 4/12



MOT #5	2021-02-11 14:20
MOT test number	445052282420
Result	✓ Passed
MOT #4	2020-02-11 12:55
MOT test number	473153844621
Result	✓ Passed
MOT #3	2019-02-13 14:37
MOT test number	886733689682
Result	✓ Passed
MOT #2	2018-02-07 14:52
MOT test number	167814924659
Result	✓ Passed
MOT #1	2017-02-09 14:20
MOT test number	432739903307
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check

Tax expired: 26 April 2024





Expires: 10 February 2025

Tax status	Expired at 26 April 2024
Days left	2 days too late
MOT expiry date	10 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
	1
Band	ı
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



HY14LGG

report date: 2024-03-28

Owner history

owner mistery	
For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	
THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	NK SIL
Plate since	
Current registration	NIX SIL
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-03-05
Last registration	2024-02-02
Complete history	See info



Registration #1	2014-03-05	29 mi
Registration #2	2017-02-09	11.787 mi
Registration #3	2018-02-07	18.886 mi
Registration #4	2019-02-13	27.134 mi
Registration #5	2020-02-11	34.780 mi
Registration #6	2021-02-11	37.921 mi
Registration #7	2021-02-11	37.921 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

The HYUNDAI factory car options list is only available in the premium report.		

S0225 Air conditioning

S0295

50482

\$0501 \$0566

S0567

S0569

View the complete HYUNDAI factory list for this vehicle <u>here</u>.

More info >

Safety ratings

NCAP rating	****
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1880 mm
Height	1690 mm
Length	4690 mm
Wheel base	2700 mm
Kerb weight	2001 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	64 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number D4HBDU883257