





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	SCIROCCO TDI BLUEMOTION TECHNOLOGY
Colour	White
Year of manufacture	2013
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	67.3 mpg
Consumption combined	55.4 mpg
CO2 emission	118 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history


Entry 2

Date 2022-01-06

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Listing price

Date	2021-02-06
Pictures	10

View report









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

B 4	\sim $-$			
10.71	α	h	sto	rv
101	() I		510	II V
	•		-	. ,

MOT expiry date	2023-09-06
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #8	2022-09-07 10:00
MOT test number	953490503600
Result	✓ Passed
Next expiry date	2023-09-06

MOT #7	2021-10-13 16:16
MOT test number	918889993437
Result	✓ Passed

MOT #6	2020-09-23 08:01
MOT test number	109908818448
Result	✓ Passed
Advice Front tyres inner edges perrished	

MOT #5	2019-09-20 10:22
MOT test number	936460196480
Result	✓ Passed
Advice Discs corroded,, front tyres low n perished,, nsr tyre as cuts not to cords	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

156608356127

Result

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (iii))

MOT #3 2018-09-25 11:25 **MOT** test number 485002659041 Result × Failed **Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice Fail** Nearside Side repeater not working (4.4.1 (a) (ii))

MOT test number

Result

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

 MOT #1
 2016-10-20 13:06

 MOT test number
 304962581277

 Result
 ✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check





Expired: 6 September 2023

Tax status	Valid until 1 September
Days left	126
MOT expiry date	6 September 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2

Date	
Category	





Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dov here.	

	More info >
Plate changes See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK WIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-09-27
Last registration	2022-09-07
Complete history	See info



Registration #1	2013-09-27	20 mi
Registration #2	2016-10-20	54.117 mi
Registration #3	2017-09-20	60.423 mi
Registration #4	2018-09-25	60.491 mi
Registration #5	2018-09-25	60.491 mi
Registration #6	2019-09-20	60.558 mi
Registration #7		11.777 es
Registration #8		71.777 es
Registration #9		11.177 es
Registration #10		11.177 es
Registration #11		71.777 mg

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Adult	87%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	2
CarChack caluk	nago 11/1:

CarCheck.co.uk page 11/11

Number of seats	4
Number of axles	2
Engine number	CFHC520511