





General information

Make	MAZDA
Model	3 D SPORT
Colour	Blue
Year of manufacture	2009
Top speed	132 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 1.800 rpm
Engine capacity	2.183 сс
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F







DHDL Automotive ***** red by **ZAUtoTrader**

1

Po

Internet history

E	intrv	1

Date

2021-02-01

7

59 VIII

Pictures

Listing price

View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-05-14
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	21
Total items failed	4

MOT #14	2023-05-15 08:40
MOT test number	613388536717
Result	✓ Passed
Next expiry date	2024-05-14

MOT #13	2022-02-15 09:19
MOT test number	154514713900
Result	🗸 Passed
Advice Oil leak, but not excessive Engine (8.4.1 (a) (i))	

MOT #12	2022-02-14 15:07
MOT test number	148770482568
Result	🗙 Failed
Fail Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge Worn o cords wearing through (5.2.3 (e))	n inner edge close to
Advice Oil leak, but not excessive Engine (8.4.1 (a) (i))	

MOT #11	2021-02-12 11:29
MOT test number	286911016253
Result	✓ Passed





MOT #10		2020-07-22 10:34
MOT test n	umber	413858340385
Result		✓ Passed
	Central Oil leak, but not excessive Engine oil leak (8.4.1 (a) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #9		2019-07-10 14:40
MOT test	number	342627879903
Result		✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #8	2018-07-31 12:13
MOT test number	658943369827
Result	✓ Passed

MOT #7		2017-08-07 11:54
MOT test	number	873477678946
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear wiper split	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)	





MOT #6		2016-08-10 12:09
MOT test	number	585037249960
Result		✓ Passed
Advice	Offside Rear tyre cracked	
Advice output (1.	Offside Rear Rear position lamp(s) has a product on the lens but not advers 1.A.3d)	sely affecting light
Advice	Nearside Front tyre cracked	
Advice	Nearside Rear tyre cracked	
Advice	Front Windscreen has damage to an area less than a 10mm circle within zo	one 'A' (8.3.1a)
Advice	Offside Front tyre cracked	

MOT #5	2015-08-20 08:55
MOT test number	413551619304
Result	✓ Passed

MOT #4	2015-	08-20 08:55
MOT test number	366	5375848785
Result		🗙 Failed
Pass with rectification	Nearside Rear Stop lamp not working (1.2.1b)	
Pass with rectification	Nearside Rear Direction indicator not working (1.4.A.2c)	
Pass with rectification	Nearside Rear Rear position lamp(s) not working side light (1.1.A.3b)	

MOT #3	2014-08-15 13:27
MOT test number	586497124266
Result	✓ Passed

MOT #2	2013-08-23 12:45
MOT test number	276435633243
Result	✓ Passed





MOT #1	2012-08-24 17:26
MOT test number	209247132266
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 February 2025	MOT Expires: 14 May 2024
Tax status	Valid until 1 February
Days left	277
MOT expiry date	14 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Damage 2	E E H - S - A
Date	*
Category	AMP.
Туре	

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-09-11
Last registration	2023-05-15
Complete history	See info



Registration #1	2009-09-11	8 mi
Registration #2	2012-08-24	23.286 mi
Registration #3	2013-08-23	31.222 mi
Registration #4	2014-08-15	34.820 mi
Registration #5	2015-08-20	37.100 mi
Registration #6	2015-08-20	37.100 mi
Registration #7	2016-08-10	41.811 mi
Registration #8	2017-08-07	47.996 mi
Registration #9		11.177 mi
Registration #10		11.777 esi
Registration #11		11.777 esi
Registration #12		10. 200 est
Registration #13		11.117 mi
Registration #13 Registration #14		10.000 est
-		10.000 est 10.000 est 10.000 est





Safety ratings

NCAP rating	****
Adult	86%
Children	84%
Pedestrian	51%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight	
Width	2002 mm
Height	1470 mm
Length	4490 mm
Wheel base	2640 mm
Kerb weight	1450 kg
Max. allowed weight	1965 kg
Additional information	
Additional information Fuel tank capacity	55 I
	55 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5