



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	107 URBAN
Colour	Red
Year of manufacture	2007
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-06-08
Pictures	37
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-30
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	41
Total items failed	5

MOT #202023-06-13 13:11

MOT test number523161870742

Result✓ Passed

Next expiry date2024-06-30

- AdviceNearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceNearside Front Suspension component mounting prescribed area damaged but not considered excessive Sill And Wing (5.3.6 (a) (i))
- AdviceOffside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceOffside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- AdviceOffside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceNearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #19**

2023-06-06 11:28

MOT test number

544673330218

Result**✗ Failed****MAJOR** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** O/s front tyre 3.5m**MAJOR** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** N/s front tyre 2.5m**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Rear Brake pipe corroded, covered in grease or other material both (1.1.11 (c))**Advice** Damage to n/s front outer sill/wheel arch**Advice** Offside Rear Nail in tyre**Advice** O/s rear tyre 3m**MOT #18**

2022-07-01 10:22

MOT test number

506692483412

Result**✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #17**

2021-06-03 16:39

MOT test number

625683103530

Result**✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2021-01-12 17:01

MOT test number

608831178705

Result

✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15**

2021-01-12 14:25

MOT test number

380917719155

Result

✗ Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Driver's airbag obviously inoperative Light on (7.1.5 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Rear Exhaust has a major leak of exhaust gases Box (6.1.2 (a))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #14**

2020-01-17 13:22

MOT test number

299050839919

Result

✓ Passed

MOT #13

2019-01-04 16:49

MOT test number

996306806481

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively rusty inside (1.1.14 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2019-01-03 13:41**MOT test number** 736960903131**Result** ✗ Failed**MAJOR** Central Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively rusty inside (1.1.14 (a) (ii))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**MAJOR** Engine MIL inoperative or indicates a malfunction light on (8.2.1.2 (h))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #11** 2018-01-19 15:43**MOT test number** 357372610585**Result** ✓ Passed**MOT #10** 2017-01-20 16:39**MOT test number** 537237769797**Result** ✓ Passed**MOT #9** 2016-01-14 17:21**MOT test number** 814896474012**Result** ✓ Passed

**MOT #8** 2016-01-14 14:00**MOT test number** 696413205963**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2015-01-16 15:37**MOT test number** 386906815020**Result** ✓ Passed**MOT #6** 2015-01-12 11:00**MOT test number** 788942815044**Result** ✗ Failed**Fail** Electronic power steering warning lamp indicates a failure in the system (2.3.8)**Fail** Nearside Stop lamp not working (1.2.1b)**MOT #5** 2013-10-23 14:53**MOT test number** 636566693273**Result** ✓ Passed**MOT #4** 2013-10-23 13:23**MOT test number** 906396293214**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)



MOT #3	2012-10-25 09:26
MOT test number	186939192266
Result	✓ Passed
Advice	Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

MOT #2	2011-10-24 10:15
MOT test number	536847291285
Result	✓ Passed

MOT #1	2010-10-22 09:39
MOT test number	111605990286
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
30 June 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	30 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-10-31
Last registration	2023-06-13
Complete history	See info



Registration #1	2007-10-31	11 mi
Registration #2	2010-10-22	13.652 mi
Registration #3	2011-10-24	17.321 mi
Registration #4	2012-10-25	21.221 mi
Registration #5	2013-10-23	27.001 mi
Registration #6	2013-10-23	27.001 mi
Registration #7	2015-01-12	36.655 mi
Registration #8	2015-01-16	36.656 mi
Registration #9	2016-01-14	39.307 mi
Registration #10	2016-01-14	39.308 mi
Registration #11	2017-01-20	41.754 mi
Registration #12	2018-01-20	45.277 mi
Registration #13	2018-01-20	45.277 mi
Registration #14	2018-01-20	45.277 mi
Registration #15	2018-01-20	45.277 mi
Registration #16	2018-01-20	45.277 mi
Registration #17	2018-01-20	45.277 mi
Registration #18	2018-01-20	45.277 mi
Registration #19	2018-01-20	45.277 mi
Registration #20	2018-01-20	45.277 mi
Registration #21	2018-01-20	45.277 mi
Registration #22	2018-01-20	45.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	825 kg
Max. allowed weight	1190 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

Engine number

5379325