





## General information

Make	HYUNDAI	
Model	140 CRDI STYLE BLUE DRIVE	
Colour	White	
Year of manufacture	2013	
Top speed 124 mph		
<b>0 - 60 mph</b> 10.6 seconds		
Gearbox	6 speed Manual	

## Engine & fuel consumption

Power	134 BHP	
Max. torque	325 Nm at 2.500 rpm	
Engine capacity	1.685 cc	
Cylinders	4	
Fuel type	Diesel	
Consumption city	53.3 mpg	
Consumption extra urban	68.9 mpg	
Consumption combined	62.8 mpg	
CO2 emission	119 g/km	
CO2 label	С	







Internet history	
Entry 1	
Date	2021-07-01
Pictures	0
Listing price	View report

source: cargurus.co.uk



## MOT history

MOT expiry date	2024-06-15
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	12
Total items failed	2

MOT #10	2023-06-09 07:55
MOT test number	767026058155
Result	✓ Passed
Next expiry date	2024-06-15

MOT #9	2022-06-16 14:16
MOT test number	480482776116
Result	✓ Passed

MOT #8	2022-06-16 11:58
MOT test number	866066144616
Result	🗙 Failed
Fail     Nearside Rear Brake pipe excessively corroded (1.1.11 (c))	

MOT #7	2021-07-20 11:23
MOT test number	736598125569
Result	✓ Passed





MOT #6	2	2020-05-25 14:15
MOT test	number	501627329551
Result		✓ Passed
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c	))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Rear Brake pad(s) wearing thin offiside and nearside (1.1.13 (a) (ii))	
Advice	Rear Service brake binding but not excessively offside and nearside $(1.2.1 (f))$	

MOT #5	2020-05-25 08:12
MOT test number	126205511548
Result	× Failed
Advice Rear Service brake binding but not excessively offside and nearside (1.2.1 (f)	)
<b>Fail</b> Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Rear Brake pad(s) wearing thin offiside and nearside (1.1.13 (a) (ii))	

MOT #4	2019-06-01 11:17
MOT test number	156166315507
Result	✓ Passed





MOT #3		2018-02-12 10:36
MOT test	number	330374674997
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Rear nearside / offside brakes slightly binding	
Advice	Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)	
MOT #2		2017-02-23 16:37
MOT test	number	605378968165
Result		✓ Passed
MOT #1		2016-02-25 15:29
MOTHER		020600616204

**MOT test number** 838609616384

Result

🗸 Passed



Tax & MOT check

Taxed	<b>Expires:</b> 15 June 2024	✓ МОТ
Tax status		Valid until 1 July
Days left		62
MOT expiry date		15 June 2024
Full MOT history		See MOT history
Tax calculation		

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

-
AMP
- A

#### Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
**********	
*******	
******	
*********	
*******	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	
Plate since	
Carrent registration	
Plate since	





#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-03-01
Last registration	2023-06-09
Complete history	<u>See info</u>



Registration #1	2013-03-01	18 mi
Registration #2	2016-02-25	33.121 mi
Registration #3	2017-02-23	41.339 mi
Registration #4	2018-02-12	50.991 mi
Registration #5	2019-06-01	61.932 mi
Registration #6	2020-05-25	71.459 mi
Registration #7		11.777 mi
Registration #7 Registration #8		10.000 est
		01.000 est 01.000 est 01.000 est
Registration #8		00.000 est 0.000 est 00.000 est 00.000 est
Registration #8 Registration #9		01.000 460 01.000 460 01.000 460 01.000 460 01.000 460





## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
\$0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight	
Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1648 kg
Max. allowed weight	2120 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

#### **Engine number**

# 2

D4FDCU263340