



**CI3JAO**

report date: 2024-03-28

General information

Make	JAGUAR
Model	XKR
Colour	Silver
Year of manufacture	2006
Top speed	155 mph
0 - 60 mph	4.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	420 BHP
Max. torque	560 Nm at 4.000 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	14.8 mpg
Consumption extra urban	32.8 mpg
Consumption combined	23.0 mpg
CO2 emission	294 g/km
CO2 label	M






Internet history

Entry 1

Date	2021-09-04
Pictures	8
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-21
MOT pass rate	93 %
MOT passed	14
Failed MOT tests	1
Total advice items	21
Total items failed	2

MOT #15	2023-09-22 09:28
MOT test number	437908945274
Result	✓ Passed
Next expiry date	2024-09-21
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14**

2022-06-10 13:27

**MOT test number**

680187569631

**Result**

✓ Passed

- Advice** Offside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Front bush (5.3.4 (a) (i))
- Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement  
(5.3.4 (a) (i))
- Minor** Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Offside Rear Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Front bush (5.3.4 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement  
(5.3.4 (a) (i))
- Minor** Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Nearside Rear Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #13**

2021-04-01 09:15

**MOT test number**

321423098169

**Result**

✓ Passed

**MOT #12**

2020-02-18 10:24

**MOT test number**

649314087132

**Result**

✓ Passed

**MOT #11**

2019-02-14 11:09

**MOT test number**

623190831908

**Result**

✓ Passed

- Advice** Under trays fitted obscuring some underside components

**MOT #10** 2019-02-14 11:09**MOT test number** 525317934405**Result** ✗ Failed**Advice** Under trays fitted obscuring some underside components**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**MOT #9** 2018-02-09 10:05**MOT test number** 604028944443**Result** ✓ Passed**MOT #8** 2017-02-25 09:38**MOT test number** 562823284433**Result** ✓ Passed**MOT #7** 2015-12-11 11:52**MOT test number** 281553328645**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front tyre has large cracks on inner and outer sidewall - cord not showing**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-11-25 16:10**MOT test number** 649159824369**Result** ✓ Passed

**MOT #5** 2013-12-04 12:59**MOT test number** 546878333328**Result** ✓ Passed**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #4** 2012-11-28 15:54**MOT test number** 868793932380**Result** ✓ Passed**MOT #3** 2011-12-06 16:03**MOT test number** 796700841301**Result** ✓ Passed**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #2** 2010-12-15 12:15**MOT test number** 254789240399**Result** ✓ Passed**MOT #1** 2009-12-10 17:01**MOT test number** 474974549405**Result** ✓ Passed



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >





Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2006-12-21
Last registration	2023-09-22
Complete history	<a href="#">See info</a>



Registration #1	2006-12-21	20 mi
Registration #2	2009-12-10	35.242 mi
Registration #3	2010-12-15	39.891 mi
Registration #4	2011-12-06	46.269 mi
Registration #5	2012-11-28	51.197 mi
Registration #6	2013-12-04	54.715 mi
Registration #7	2014-11-25	58.668 mi
Registration #8	2015-12-11	65.657 mi
Registration #9	2017-02-25	70.788 mi
Registration #10	2019-05-20	75.277 mi
Registration #11	2019-05-20	75.277 mi
Registration #12	2019-05-20	75.277 mi
Registration #13	2019-05-20	75.277 mi
Registration #14	2019-05-20	75.277 mi
Registration #15	2019-05-20	75.277 mi
Registration #16	2019-05-20	75.277 mi
Registration #17	2019-05-20	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1892 mm
Height	1322 mm
Length	4791 mm
Wheel base	2752 mm
Kerb weight	1665 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	06060309559G