



report date: 2024-03-29

General information

Make	FORD
Model	C-MAX ZETEC 100
Colour	Silver
Year of manufacture	2009
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-10-02
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-27
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	17
Total items failed	16

MOT #20	2023-09-21 17:47
MOT test number	576524867989
Result	✓ Passed
Next expiry date	2024-09-27
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #19	2023-09-21 07:07
MOT test number	445249394909
Result	✗ Failed
Fail	Offside Front Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Offside Front Anti-roll bar linkage ball joint likely to become detached (5.3.4 (a) (ii))

MOT #18	2022-09-23 08:11
MOT test number	596774546478
Result	✓ Passed

**MOT #17** 2021-09-28 08:52**MOT test number** 233354684903**Result** ✓ Passed**MOT #16** 2021-09-22 10:37**MOT test number** 624039448565**Result** ✗ Failed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2021-01-06 11:11**MOT test number** 516459306120**Result** ✓ Passed**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #14** 2020-01-29 14:35**MOT test number** 352565969233**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn inner edge. (5.2.3 (e))**Advice** Nearside Rear Valve stem slightly damaged Perishing. (5.2.3 (j))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm worn inner edge. (5.2.3 (e))

**MOT #13** 2019-02-08 10:52**MOT test number** 676844807037**Result** ✓ Passed**MOT #12** 2019-02-07 11:41**MOT test number** 201580328919**Result** ✗ Failed

- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Fail** Windscreen washer provides insufficient washer liquid both (3.5 (a))
- Fail** Nearside Rear Suspension arm pin or bush likely to become detached trailing arm bush bond failed (5.3.4 (a) (ii))
- Fail** Suspension arm pin or bush excessively worn both front arms rear bushes deteriorated and movement (5.3.4 (a) (i))
- Fail** Front Exhaust system insecure (6.1.2 (a))
- Advice** Offside Rear trailing arm bush bond failing

MOT #11 2018-03-21 15:28**MOT test number** 635726703553**Result** ✓ Passed

- Advice** Offside Front Brake pad(s) wearing thin very close (3.5.1g)
- Advice** Nearside Front Brake pad(s) wearing thin very close (3.5.1g)

MOT #10 2017-03-30 06:51**MOT test number** 396256292802**Result** ✓ Passed**MOT #9** 2017-03-29 10:35**MOT test number** 857565608495**Result** ✗ Failed

- Fail** Nearside Front Front wheel bearing rough when rotated (2.5.A.2)

**MOT #8** 2016-03-31 11:53**MOT test number** 764982584298**Result** Passed**MOT #7** 2016-03-31 11:53**MOT test number** 675843151653**Result** Failed**Pass with rectification** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**MOT #6** 2015-04-04 11:57**MOT test number** 116554395074**Result** Passed**MOT #5** 2015-04-04 11:57**MOT test number** 889494895019**Result** Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #4** 2014-04-04 15:03**MOT test number** 849794994001**Result** Passed**MOT #3** 2013-03-27 12:53**MOT test number** 886166283066**Result** Passed



MOT #2	2012-03-30 16:03
MOT test number	138190892087
Result	✓ Passed

MOT #1	2012-03-28 15:23
MOT test number	147158582463
Result	✗ Failed
Fail	Nearside Rear Passenger's seat cannot be secured in the upright position. (6.2.A.2)
Fail	Nearside Rear Wheel nut(s) missing (4.2.A.1e)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
27 September 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	27 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	YK09KPF
Plate since	2019-03-29
Current registration	YK09KPF
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-04-07
Last registration	2023-09-21
Complete history	See info



Registration #1	2009-04-07	19 mi
Registration #2	2012-03-28	23.989 mi
Registration #3	2012-03-30	23.990 mi
Registration #4	2013-03-27	31.339 mi
Registration #5	2014-04-04	37.406 mi
Registration #6	2015-04-04	44.242 mi
Registration #7	2016-03-31	48.918 mi
Registration #8	2016-03-31	48.918 mi
Registration #9	2017-03-29	54.262 mi
Registration #10	2017-03-30	54.262 mi
Registration #11	2018-03-21	59.958 mi
Registration #12	2019-03-20	65.654 mi
Registration #13	2019-03-20	65.654 mi
Registration #14	2019-03-20	65.654 mi
Registration #15	2019-03-20	65.654 mi
Registration #16	2019-03-20	65.654 mi
Registration #17	2019-03-20	65.654 mi
Registration #18	2019-03-20	65.654 mi
Registration #19	2019-03-20	65.654 mi
Registration #20	2019-03-20	65.654 mi
Registration #21	2019-03-20	65.654 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1372 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9G49373