





report date: 2024-03-28

General information

Make	KIA
Model	SORENTO
Colour	Silver
Year of manufacture	2010
Gearbox	-

Engine & fuel consumption

Engine capacity	2.497 cc
Fuel type	Diesel
CO2 emission	228 g/km
CO2 label	L



CarCheck.co.uk page 1/13



Internet history

Entry 2

Date 2021-09-30

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-09-12

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-08-30
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	18
Total items failed	2

MOT #14	23-08-16 08:14
MOT test number	979431533138
Result	✓ Passed
Next expiry date	2024-08-30
Advice Surface corrosion front,rear suspension,rear axle,o/s n/s chassis,n/s/r inner sill,towba	r

MOT #13	2022-08-09 07:36
MOT test number	808904656655
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #12	2021-08-31 10:57
MOT test number	513170032185
Result	✓ Passed

MOT #11	2020-10-13 10:17
MOT test number	867572547353
Result	✓ Passed

CarCheck.co.uk page 3/13



MOT #10

MOT test number

485856182629

Result

Advice Front wipers smeary

MOT #9 2018-10-05 10:12 **MOT test number** 408921554318 ✓ Passed Result MOT #8 2017-10-11 11:15 **MOT test number** 463025176095 Result ✓ Passed **Advice** Front & rear tyre worn/almost bald on inner edge **Advice** Front & rear tyres perished

MOT #7	2016-10-11 09:30
MOT test number	558601118207
Result	✓ Passed
Advice All 4 tyre perished	

CarCheck.co.uk page 4/13



MOT #6 2015-10-20 09:18

MOT test number 753715659554

Result ✓ Passed

Advice Nearside Rear tyre heavily worn on inside edge

Advice Nearside Front tyre heavily perished

Advice Nearside Rear tyre heavily perished

Advice Offside Rear tyre heavily worn on inside edge

Advice Offside Front tyre heavily perished

Advice Offside Rear tyre heavily perished

MOT #5 2014-10-27 14:04

MOT test number 467760704401

Result \(\sqrt{Passed} \)

Notice Both front tyres worn more on inner edges

MOT #4 2014-10-27 14:04

MOT test number 717080604397

Result × Failed

Notice Both front tyres worn more on inner edges

Pass with rectification Offside Front Front position lamp(s) not working (1.1.A.3b)

Pass with rectification Nearside Front Headlamp aim too low (1.8)

MOT #3 2013-11-01 14:58

MOT test number 205945003387

Result ✓ Passed

CarCheck.co.uk page 5/13



MOT test number

497685283169

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2013-02-15 09:17
MOT test number	325486243038
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	30 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

*	
For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report	

THE STREET STREE	
	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	
Correct registration	UK SIN
Plate since	
Current registration	RIK SIK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-01
Last registration	2023-08-16
Complete history	See info



Registration #1	2010-03-01	21 mi
Registration #2	2013-02-15	12.604 mi
Registration #3	2013-07-04	14.420 mi
Registration #4	2013-11-01	17.800 mi
Registration #5	2014-10-27	26.943 mi
Registration #6	2015-10-20	33.571 mi
Registration #7	2016-10-11	39.607 mi
Registration #8	2017-10-11	46.436 mi
Registration #9		11.177 es
Registration #10		11.777 es
Registration #11		11.177 es
Registration #12		11.177 es
Registration #13		9.777 es
Registration #14		0.00 44
Registration #15		0.0746

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	87%
Children	84%
Pedestrian	44%
Safety systems	71%
Overall rating	76%
Video	see crash video



Additional information

Number of seats	5
Engine number	D4CB7284057

CarCheck.co.uk page 13/13