



report date: 2024-03-28

General information

Make	CITROEN
Model	DS4 HDI DSTYLE
Colour	White
Year of manufacture	2011
Top speed	132 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E






Internet history

Entry 2


Date	2021-08-05
Pictures	34
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-08-04
Pictures	34
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

**MOT expiry date** 2023-08-02**MOT pass rate** 60 %**MOT passed** 9**Failed MOT tests** 6**Total advice items** 29**Total items failed** 18**MOT #15** 2023-08-07 11:29**MOT test number** 353068896765**Result** ✗ Failed**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Nearside Front Inner Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** OBDII Would Not Connect To Vehicle For Engine Speed And Oil Temperature**Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))**Advice** Front Brake disc worn, but not excessively Both Sides (1.1.14 (a) (i))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**MOT #14** 2022-08-03 13:07**MOT test number** 855105784342**Result** ✓ Passed**Advice** Engine cover & undertray fitted**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear tyre perished

**MOT #13** 2021-08-03 16:04**MOT test number** 641919729765**Result** ✓ Passed**MOT #12** 2020-11-02 13:05**MOT test number** 358690873722**Result** ✓ Passed**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge tyre shoulder worn and 4.mm remainder (5.2.3 (e))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #11** 2020-10-27 12:26**MOT test number** 950246836665**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge tyre shoulder worn and 4.mm remainder (5.2.3 (e))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #10** 2019-10-28 14:37**MOT test number** 921052414873**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #9**

2019-10-24 10:55

**MOT test number**

581475925743

**Result****✗ Failed**

**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Fail** Electronic parking brake control defective so that it cannot be satisfactorily operated (1.1.6 (d))

**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Fail** Emissions not tested dip stick incomplete- no oil showing (8.2.2.2 (e))

**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8**

2018-10-26 13:30

**MOT test number**

446506228821

**Result****✓ Passed**

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Dip stick broken

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2018-10-26 12:10**MOT test number** 286398923750**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Dip stick broken**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**MOT #6** 2017-10-27 15:54**MOT test number** 413868672759**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit Approximately 2mm (4.1.E.1)**Advice** Items removed from driver's view prior to test Air freshener hanging from rear view mirror**MOT #5** 2016-10-28 10:39**MOT test number** 218032599564**Result** ✓ Passed**Advice** All tyres wearing on inner edges**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2015-10-29 15:30**MOT test number** 222271117135**Result** ✓ Passed

**MOT #3** 2015-10-29 15:30**MOT test number** 521462407164**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2014-10-17 10:01**MOT test number** 689380494274**Result** ✓ Passed**MOT #1** 2014-10-16 12:35**MOT test number** 848479884257**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Nail in nearside rear tyre



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✗  
**MOT**  
**Expired:**  
2 August 2023

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	2 August 2023
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>GK61NXJ</b>
Plate since	2019-03-28
Current registration	<b>GK61NXJ</b>
Plate since	2019-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-10-05
Last registration	2023-08-07
Complete history	<a href="#">See info</a>



Registration #1	2011-10-05	15 mi
Registration #2	2014-10-16	18.975 mi
Registration #3	2014-10-17	19.003 mi
Registration #4	2015-10-29	27.011 mi
Registration #5	2015-10-29	27.011 mi
Registration #6	2016-10-28	38.840 mi
Registration #7	2017-10-27	49.294 mi
Registration #8	2018-10-26	56.792 mi
Registration #9	2018-10-26	56.792 mi
Registration #10	2019-10-26	56.792 mi
Registration #11	2019-10-26	56.792 mi
Registration #12	2019-10-26	56.792 mi
Registration #13	2019-10-26	56.792 mi
Registration #14	2019-10-26	56.792 mi
Registration #15	2019-10-26	56.792 mi
Registration #16	2019-10-26	56.792 mi
Registration #17	2019-10-26	56.792 mi
Registration #18	2019-10-26	56.792 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	80%
Pedestrian	43%
Safety systems	97%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1810 mm
Height	1523 mm
Length	4275 mm
Wheel base	2612 mm
Kerb weight	1320 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYYF4046748