



report date: 2024-03-28

General information

Make	FIAT
Model	PANDA POP
Colour	White
Year of manufacture	2013
Top speed	102 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	120 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-07-11
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	15
Total items failed	2

MOT #10	2023-07-04 13:37
MOT test number	178054036282
Result	✓ Passed
Next expiry date	2024-07-11

MOT #9	2022-06-29 13:41
MOT test number	342919337580
Result	✓ Passed

MOT #8	2021-07-12 14:45
MOT test number	222243594713
Result	✓ Passed

MOT #7	2020-09-03 10:44
MOT test number	890342768450
Result	✓ Passed

MOT #6	2020-09-01 14:03
MOT test number	578539897276
Result	✗ Failed

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Nearside Front SERVICE BRAKE LAGGING SLIGHTLY IN OPERATION

**MOT #5** 2019-09-01 10:53**MOT test number** 848042440732**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2019-09-01 10:53**MOT test number** 480869318975**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #3** 2018-09-02 09:46**MOT test number** 125223174120**Result** ✓ Passed**Advice** Both sides rear shock absorber's upper bush slightly worn**Advice** Exhaust has a minor leak of exhaust gases back-box (6.1.2 (a))**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))



MOT #2	2017-08-31 13:06
MOT test number	178740096172
Result	✓ Passed
Advice	Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4)
Advice	Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)

MOT #1	2016-08-31 08:45
MOT test number	595554727049
Result	✓ Passed
Advice	Nearside front tyre on 2mm



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
11 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	11 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-09-06
Last registration	2023-07-04
Complete history	See info



Registration #1	2013-09-06	20 mi
Registration #2	2016-08-31	31.180 mi
Registration #3	2017-08-31	35.636 mi
Registration #4	2018-09-02	40.700 mi
Registration #5	2019-09-01	45.418 mi
Registration #6	2019-09-01	45.418 mi
Registration #7	2019-09-01	45.418 mi
Registration #8	2019-09-01	45.418 mi
Registration #9	2019-09-01	45.418 mi
Registration #10	2019-09-01	45.418 mi
Registration #11	2019-09-01	45.418 mi
Registration #12	2019-09-01	45.418 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1882 mm
Height	1551 mm
Length	3653 mm
Wheel base	2300 mm
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	37 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2

Engine number

0341597