



report date: 2024-03-28

General information

|                     |                |
|---------------------|----------------|
| Make                | SUZUKI         |
| Model               | ALTO SZ        |
| Colour              | Grey           |
| Year of manufacture | 2013           |
| Top speed           | 96 mph         |
| 0 - 60 mph          | 13.5 seconds   |
| Gearbox             | 5 speed Manual |

Engine & fuel consumption

|                         |                    |
|-------------------------|--------------------|
| Power                   | 68 BHP             |
| Max. torque             | 90 Nm at 3.400 rpm |
| Engine capacity         | 996 cc             |
| Cylinders               | 3                  |
| Fuel type               | Petrol             |
| Consumption city        | 54.3 mpg           |
| Consumption extra urban | 74.3 mpg           |
| Consumption combined    | 65.7 mpg           |
| CO2 emission            | 99 g/km            |
| CO2 label               | A                  |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-02-04                  |
| Pictures      | 10                          |
| Listing price | <a href="#">View report</a> |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-10-07 |
| MOT pass rate      | 73 %       |
| MOT passed         | 8          |
| Failed MOT tests   | 3          |
| Total advice items | 10         |
| Total items failed | 5          |

|                  |                              |
|------------------|------------------------------|
| MOT #11          | 2023-09-29 11:14             |
| MOT test number  | 971106169873                 |
| Result           | ✓ Passed                     |
| Next expiry date | 2024-10-07                   |
| Advice           | General corrosion underneath |

|                 |  |
|-----------------|--|
| MOT #10         | 2022-10-07 15:17   |
| MOT test number | 151982338431   |
| Result          | ✓ Passed   |
| Minor           | Offside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))                                 |
| Minor           | Nearside Inner Drive shaft joint constant velocity boot severely deteriorated Weeping grease, small clip end (6.1.7 (g) (i)) |
| Advice          | Offside Front Brake pad(s) wearing thin Outer pad ON LIMIT. ADVISE REPLACEMENT (1.1.13 (a) (ii))                             |
| Advice          | Offside Rear Outer wheel arch damaged/distorted. No sharp edges at time of test.   |

**MOT #9** 2022-10-07 14:02**MOT test number** 914244918448**Result** ✗ Failed**Advice** Offside Front Brake pad(s) wearing thin Outer pad ON LIMIT. ADVISE REPLACEMENT (1.1.13 (a) (ii))**Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Minor** Nearside Inner Drive shaft joint constant velocity boot severely deteriorated Weeping grease, small clip end (6.1.7 (g) (i))**Advice** Offside Rear Outer wheel arch damaged/distorted. No sharp edges at time of test.**Fail** Offside Registration plate lamp missing in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Minor** Offside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #8** 2021-10-01 12:54**MOT test number** 180248000627**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #7** 2020-10-08 14:35**MOT test number** 662536982623**Result** ✓ Passed**MOT #6** 2019-03-23 08:16**MOT test number** 239997481789**Result** ✓ Passed**MOT #5** 2019-03-16 10:38**MOT test number** 110658472929**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))



|                         |   |
|-------------------------|---|
| MOT #4                  | 2018-03-27 14:02  |
| MOT test number         | 382739907930  |
| Result                  | ✓ Passed  |
| MOT #3                  | 2018-03-27 14:02  |
| MOT test number         | 660602865515  |
| Result                  | ✗ Failed  |
| Pass with rectification | Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)  |
| Pass with rectification | Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) |
| MOT #2                  | 2017-04-07 10:07  |
| MOT test number         | 325468872423  |
| Result                  | ✓ Passed  |
| MOT #1                  | 2016-01-16 08:20  |
| MOT test number         | 964165964606  |
| Result                  | ✓ Passed  |



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
7 October 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 January           |
| <b>Days left</b>        | 247                             |
| <b>MOT expiry date</b>  | 7 October 2024                  |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |                |
|--|----------------|
| <b>Vehicle class</b>                           | 48             |
| <b>Band</b>                                    | A              |
| <b>Single payment (12 months)</b>              | £ 0,00,-       |
| <b>Single six month payment</b>                | Not applicable |
| <b>Total payable by 12 monthly instalments</b> | Not applicable |



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >





Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration | EN62GZA    |
| Plate since          | 2019-09-28 |
| Current registration | EN62GZA    |
| Plate since          | 2019-09-28 |

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 13                       |
| First mileage registration | 2013-01-26               |
| Last registration          | 2023-09-29               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2013-01-26 | 20 mi     |
| Registration #2  | 2016-01-16 | 37.436 mi |
| Registration #3  | 2017-04-07 | 37.930 mi |
| Registration #4  | 2018-03-27 | 44.558 mi |
| Registration #5  | 2018-03-27 | 44.558 mi |
| Registration #6  | 2019-03-16 | 54.600 mi |
| Registration #7  | 2019-03-23 | 54.788 mi |
| Registration #8  | 2019-03-23 | 54.788 mi |
| Registration #9  | 2019-03-23 | 54.788 mi |
| Registration #10 | 2019-03-23 | 54.788 mi |
| Registration #11 | 2019-03-23 | 54.788 mi |
| Registration #12 | 2019-03-23 | 54.788 mi |
| Registration #13 | 2019-03-23 | 54.788 mi |

More info >



Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★☆                           |
| Adult          | 55%                             |
| Children       | 46%                             |
| Pedestrian     | 35%                             |
| Safety systems | 29%                             |
| Overall rating | 47%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1600 mm |
| Height              | 1470 mm |
| Length              | 3500 mm |
| Wheel base          | 2360 mm |
| Kerb weight         | 930 kg  |
| Max. allowed weight | 1250 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 35 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of seats    | 4                     |
| Number of axles    | 2                     |
| Engine number      | K10BN 1640153         |