



VE59VR0

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF SE TDI BLUEMOTION
Colour	Black
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 1.500 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	68.9 mpg





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

**MOT history**

MOT #12	2022-05-17 06:54
MOT test number	627115284365
Result	✓ Passed
Next expiry date	2023-05-16

MOT #11	2022-05-13 12:32
MOT test number	855158575768
Result	✗ Failed

- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #10	2021-05-12 11:46
MOT test number	761352637202
Result	✓ Passed

MOT #9	2020-06-17 15:55
MOT test number	224325301785
Result	✓ Passed

- Advice** Rear Tyre slightly damaged/cracking or perishing both sides 205 / 55 / 16 (5.2.3 (d) (ii))

MOT #8	2019-06-22 11:54
MOT test number	957446822986
Result	✓ Passed

**MOT #7** 2018-06-21 10:33**MOT test number** 544489065834**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** Offside Rear Nail in tyre**MOT #6** 2017-06-29 14:00**MOT test number** 599558897663**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit bald on inner edge (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit 205/55x16 bald on inner edge (4.1.E.1)**MOT #5** 2016-06-25 13:41**MOT test number** 644935949016**Result** ✓ Passed**MOT #4** 2015-07-02 11:59**MOT test number** 476563385182**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2014-12-02 09:57**MOT test number** 446856034349**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Emissions too low to test**Notice** Engine covers fitted obscuring some components in the engine bay



MOT #2	2013-12-16 11:42
MOT test number	286450353381
Result	✓ Passed

MOT #1	2013-01-14 10:19
MOT test number	986424713080
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 VE59VRO
Plate since	2019-06-29
Current registration	 VE59VRO
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-12-16
Last registration	2022-05-17
Complete history	See info



Registration #1	2009-12-16	13 mi
Registration #2	2013-01-14	37.300 mi
Registration #3	2013-12-16	45.821 mi
Registration #4	2014-12-02	50.938 mi
Registration #5	2015-07-02	52.803 mi
Registration #6	2016-06-25	58.428 mi
Registration #7	2017-06-29	67.736 mi
Registration #8	2018-05-29	75.277 mi
Registration #9	2019-05-29	85.277 mi
Registration #10	2020-05-29	95.277 mi
Registration #11	2021-05-29	105.277 mi
Registration #12	2022-05-17	115.277 mi
Registration #13	2023-05-29	125.277 mi
Registration #14	2024-03-28	135.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1840 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	CAY 152257