





report date: 2024-03-28

## General information

Make	FORD
Model	ECOSPORT ZETEC TDCI
Colour	Silver
Year of manufacture	2018
Top speed	99 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	94 BHP
Max. torque	215 Nm at 2.750 rpm
Engine capacity	1.499 сс
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	65.7 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28


## Internet history

#### Entry 2

Date 2021-06-30	
-----------------	--

Pictures 17

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-06-29	

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-01-22
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	12
Total items failed	0

MOT #5	2024-01-23 10:41
MOT test number	901792755092
Result	✓ Passed
Next expiry date	2025-01-22
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	
Advice Corrosion to rear silencer	
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge 3.5mm (5.2.3 (e))	
Advice Handbrake has little reserve travel	

MOT #4	2023-01-11 09:19
MOT test number	950625170524
Result	<b>✓</b> Passed
MOT #3	2022-01-05 12:08
MOT test number	756416062810
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

× Failed

MOT #2 2021-04-21 09:01
MOT test number 218617220564

MOT #1 2021-04-14 16:16

**MOT test number** 725717744299

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MAJOR** Windscreen washer not working (3.5 (a))

**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen not clipped

in (3.5 (a))

Result

CarCheck.co.uk page 4/11



## Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	22 January 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

## Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

## Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners d Check it in the premium report and see all owner registrations. Download the full report h		ave?
*******		
***************************************		
	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	NK NY	
Plate since		
Current registration	NK NA	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-01-08
Last registration	2024-01-23
Complete history	See info



Registration #1	2018-01-08	6 mi
Registration #2	2021-04-14	20.702 mi
Registration #3	2021-04-21	30.703 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	93%
Children	77%
Pedestrian	58%
Safety systems	55%
Overall rating	79%
Video	see crash video



# Dimensions & weight

Width	2057 mm
Height	1633 mm
Length	4017 mm
Wheel base	2519 mm
Kerb weight	1370 kg
Max. allowed weight	1760 kg

# Additional information

Fuel tank capacity	52 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/

Number of axles 2

Engine number HA85349