




report date: 2022-08-13

General information

Make	JAGUAR
Model	XK8 CONVERTIBLE
Colour	Grey
Year of manufacture	2004
Top speed	155 mph
0 - 60 mph	6.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	300 BHP
Max. torque	420 Nm at 4.100 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	16.8 mpg
Consumption extra urban	33.6 mpg
Consumption combined	24.8 mpg
CO2 emission	279 g/km
CO2 label	M






Internet history

Entry 2


Date	2021-06-19
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-19
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-29
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	33
Total items failed	7

MOT #22	2023-06-30 13:57
MOT test number	657691621324
Result	✓ Passed
Next expiry date	2024-06-29
Minor	Nearside Front Obligatory mirror slightly loose (3.3 (b) (i))

MOT #21	2022-03-03 15:57
MOT test number	988440117941
Result	✓ Passed
Advice	Wet test
Advice	Rear General corrosion underside
Advice	Front General corrosion underside

MOT #20	2022-03-02 13:26
MOT test number	745851483890
Result	✗ Failed
Advice	Front General corrosion underside
Advice	Wet test
Advice	Rear General corrosion underside
Fail	Nearside Front Inner Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting Sill (6.2.2 (d) (i))

**MOT #19**

2021-02-10 17:11

MOT test number

761386414299

Result

✓ Passed

Advice

Brake pipe corroded, covered in grease or other material all brake pipes are covered in material (1.1.11 (c))

Advice

Offside Rear Wheel bearing has slight play slight play (5.1.3 (a) (i))

Advice

Nearside Rear Wheel bearing has slight play slight play (5.1.3 (a) (i))

MOT #18

2021-02-09 12:28

MOT test number

773283610391

Result

✗ Failed

Advice

Brake pipe corroded, covered in grease or other material all brake pipes are covered in material (1.1.11 (c))

Advice

Offside Rear Wheel bearing has slight play slight play (5.1.3 (a) (i))

Advice

Nearside Rear Wheel bearing has slight play slight play (5.1.3 (a) (i))

Fail

Nearside Front Lower Suspension arm pin or bush excessively worn outer ball joint has excessively play (5.3.4 (a) (i))

MOT #17

2020-02-27 12:55

MOT test number

443223026206

Result

✓ Passed

Advice

Noise from offside front suspension no obvious fault found

Advice

Brake pipe corroded, covered in grease or other material covered in underseal unable to fully inspect (1.1.11 (c))

Advice

Engine and underbody covers fitted unable to fully inspect

MOT #16

2019-03-04 16:33

MOT test number

764891305788

Result

✓ Passed

**MOT #15** 2018-04-23 10:53**MOT test number** 846225680902**Result** ✓ Passed**MOT #14** 2018-04-11 14:45**MOT test number** 986049265555**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)**MOT #13** 2017-01-17 11:26**MOT test number** 891258421741**Result** ✓ Passed**MOT #12** 2016-01-20 10:27**MOT test number** 358218985704**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Subframe mounting prescribed area is corroded but not considered excessive floor pan (2.4.A.3)**MOT #11** 2014-10-07 15:03**MOT test number** 446340484296**Result** ✓ Passed**MOT #10** 2013-09-12 12:05**MOT test number** 327145653244**Result** ✓ Passed

**MOT #9** 2013-09-09 11:11**MOT test number** 947842753258**Result** ✗ Failed**Fail** Nearside Front Shock absorber has an excessively worn bush (2.7.4)**MOT #8** 2012-08-16 09:46**MOT test number** 118689922224**Result** ✓ Passed**Advice** Offside Inner Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2011-08-31 09:36**MOT test number** 885153341240**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** R/n/s and r/o/s inner drive shaft coupling flanges have play in diff

**MOT #6** 2011-08-16 10:18**MOT test number** 329518321204**Result** ✗ Failed

- Fail** Nearside Inner Front Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** F/o/s brake binding slightly
- Advice** Offside Inner Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Inner Front Tyre has ply or cords exposed (4.1.D.1b)
- Notice** R/n/s and r/o/s inner drive shaft flanges have play in diff
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2010-08-26 09:48**MOT test number** 643968530220**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** F/o/s brake binding slightly
- Advice** Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2009-08-13 10:47**MOT test number** 592915629293**Result** ✓ Passed**MOT #3** 2009-01-28 10:02**MOT test number** 141428329053**Result** ✓ Passed



MOT #2	2008-01-25 14:00
---------------	------------------

MOT test number	444835628000
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2007-02-02 16:15
---------------	------------------

MOT test number	630713037015
------------------------	--------------

Result	✓ Passed
---------------	----------



Damage history


Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-01-29
Last registration	2023-06-30
Complete history	See info



Registration #1	2004-01-29	19 mi
Registration #2	2007-02-02	17.261 mi
Registration #3	2008-01-25	21.836 mi
Registration #4	2009-01-28	24.647 mi
Registration #5	2009-08-13	25.931 mi
Registration #6	2010-08-26	27.796 mi
Registration #7	2011-08-16	28.345 mi
Registration #8	2011-08-31	28.434 mi
Registration #9	2012-08-16	30.496 mi
Registration #10	2013-09-09	31.148 mi
Registration #11	2013-09-12	31.148 mi
Registration #12	2014-10-07	31.917 mi
Registration #13	2016-01-20	36.255 mi
Registration #14	2016-05-20	36.255 mi
Registration #15	2016-05-20	36.255 mi
Registration #16	2016-05-20	36.255 mi
Registration #17	2016-05-20	36.255 mi
Registration #18	2016-05-20	36.255 mi
Registration #19	2016-05-20	36.255 mi
Registration #20	2016-05-20	36.255 mi
Registration #21	2016-05-20	36.255 mi
Registration #22	2016-05-20	36.255 mi
Registration #23	2016-05-20	36.255 mi
Registration #24	2016-05-20	36.255 mi
Registration #25	2016-05-20	36.255 mi

**Dimensions & weight**

Width	2015 mm
Height	1306 mm
Length	4760 mm
Wheel base	2588 mm
Kerb weight	1685 kg
Max. allowed weight	2185 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	2B0312031537