





report date: 2024-03-29

General information

Make	NISSAN
Model	FIGARO
Colour	Pink
Year of manufacture	1991
Gearbox	-

Engine & fuel consumption

Engine capacity	980 cc
Fuel type	Petrol



CarCheck.co.uk page 1/14



report date: 2024-03-29


Internet history


Entry 3


Date 2021-12-14

Pictures 19

Listing price <u>View report</u>










source: autotrader.co.uk

Entry 2

2021-10-18

Pictures 19

Listing price <u>View report</u>










source: autotrader.co.uk

Entry 1

Date 2021-07-27

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-04-23
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	18
Total items failed	15

MOT #15	2023-04-24 13:59
MOT test number	149120713660
Result	✓ Passed
Next expiry date	2024-04-23
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Brake pipe corroded, covered in grease or other material front to rears (1.1.11 (c))	
Minor Registration plate lamp inoperative in the case of mu	ultiple lamps or light sources (4.7.1 (b) (i))

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #14 2023-04-24 12:24

MOT test number 496445041155

Result X Failed

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Offside Windscreen washer not working (3.5 (a))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Brake pipe corroded, covered in grease or other material front to rears (1.1.11 (c))

Fail Offside Rear Body panel corroded and likely to cause injury wing (6.2.1 (a) (i))

Fail Offside Rear fog lamp not working (4.5.1 (a) (ii))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill end (5.3.6 (a) (i))

Fail Nearside Rear Body panel corroded and likely to cause injury wing (6.2.1 (a) (i))

MOT #13 2022-04-07 13:06

MOT test number 415928974241

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Integral body structure is corroded but structural rigidity is not significantly reduced boot floor (6.1.1 (c) (i))

Advice Rear Brake pipe corroded, covered in grease or other material of front to rear x2 (1.1.11 (c))

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #12 2022-04-06 09:34

MOT test number 494687917863

Result X Failed

Advice Rear Brake pipe corroded, covered in grease or other material of front to rear x2 (1.1.11 (c))

Fail Offside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

Fail Rear Fuel pipe leaking (6.1.3 (b) (i))

Fail Nearside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

Advice Integral body structure is corroded but structural rigidity is not significantly reduced boot floor (6.1.1 (c) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2021-04-06 11:17
MOT test number	268527054823

MOT #10	2020-03-18 15:27
---------	------------------

MOT test number 687026529740

Result ✓ Passed

MOT #9 2019-03-01 15:11

MOT test number 817422436588

MOT #8 2018-03-02 09:36

MOT test number 314128811896

Result / Passed

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Brake pipe slightly corroded marked yellow (3.6.B.2c)

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Brake pipe slightly corroded marked yellow (3.6.B.2c)

Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #5 2016-02-18 08:14 **MOT** test number 436707271902 Result ✓ Passed **MOT #4** 2016-02-17 10:02 **MOT** test number 356159518469 Result × Failed Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #3	2015-01-07 09:04
MOT test number	615067105052
Result	✓ Passed

CarCheck.co.uk page 6/14



2015-01-06 13:06 MOT #2

MOT test number 915346105002

Result

× Failed

Fail Offside Front Front suspension ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Nearside Front Front suspension ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #1 2014-01-21 10:18

MOT test number 216681124036

Result ✓ Passed

Advice

Nearside Rear wheel bearing has slight play (2.6.2)

Advice

Offside Front Steering rack gaiter deteriorated (2.2.D.2d)

CarCheck.co.uk page 7/14



Tax & MOT check





Tax status Expired at 1 March 2024

Days left 58 days too late

MOT expiry date 23 April 2024

Full MOT history See MOT history

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full re		N

	More info	>
Plate changes See in this check if this NISSAN had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In kilometers
Mileage registrations	18
First mileage registration	2014-01-21
Last registration	2023-04-24
Complete history	See info



Registration #1	2014-01-21	94.674 mi
Registration #2	2015-01-06	103.831 mi
Registration #3	2015-01-07	103.831 mi
Registration #4	2016-02-17	116.729 mi
Registration #5	2016-02-18	116.729 mi
Registration #6	2017-02-20	134.002 mi
Registration #7	2017-02-20	134.002 mi
Registration #8	2018-03-02	94.065 mi
Registration #9	2019-03-01	101.244 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 esi
Registration #18		

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

S0225	Air conditioning
50295	
50482	
60501	
60566	
60567	
60569	

Additional information

Number of seats	4
Engine number	MA10

CarCheck.co.uk page 14/14