



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	VERSO VALVEMATIC T SPIRIT
Colour	Blue
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	10.4 seconds
Gearbox	7 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	180 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-09
Pictures	8
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-16
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	33
Total items failed	8

MOT #16	2023-12-18 16:18
---------	------------------

MOT test number	130510906447
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-01-16
------------------	------------

Advice	Rear support brace heavily corroded
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Vehicles internal headlight adjuster altered to recheck lights
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	All ball joint dust covers perished
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both nearside and offside (1.1.14 (a) (ii))
Advice	Rear rear under carriage corroded
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Rear Fuel Pipe/s corroded
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	All bushes perishing

**MOT #15**

2023-12-18 12:37

MOT test number

832305971662

Result**✗ Failed**

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both nearside and offside (1.1.14 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** All ball joint dust covers perished
- Fail** Nearside Headlamp aim too low (4.1.2 (a))
- Advice** Rear rear under carriage corroded
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Rear Fuel Pipe/s corroded
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** All bushes perishing
- Advice** Rear support brace heavily corroded
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Offside Headlamp aim too low (4.1.2 (a))
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Fail** Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #14

2023-01-10 12:31

MOT test number

646072164271

Result**✓ Passed**

**MOT #13** 2022-01-07 10:39**MOT test number** 530630984330**Result** ✓ Passed**Advice** Brake pad(s) wearing thin front both (1.1.13 (a) (ii))**MOT #12** 2020-12-22 11:16**MOT test number** 461290134507**Result** ✓ Passed**MOT #11** 2019-06-17 11:31**MOT test number** 527382655399**Result** ✓ Passed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**MOT #10** 2018-07-11 16:29**MOT test number** 377389297568**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Both rear tyres have some cracks on the outside edge**MOT #9** 2018-07-11 10:12**MOT test number** 717233526349**Result** ✗ Failed**Fail** All direction indicators incorrect colour (4.4.3 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Both rear tyres have some cracks on the outside edge**Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #8** 2017-07-17 10:39**MOT test number** 841431812921**Result** ✓ Passed**MOT #7** 2016-08-20 13:56**MOT test number** 778716019523**Result** ✓ Passed**MOT #6** 2016-08-20 09:31**MOT test number** 655962326963**Result** ✗ Failed**Advice** Nearside Rear Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2015-09-19 08:30**MOT test number** 225714538861**Result** ✓ Passed**MOT #4** 2015-09-19 08:30**MOT test number** 581968902325**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2014-09-27 12:46**MOT test number** 588240474226**Result** ✓ Passed**MOT #2** 2013-09-27 10:02**MOT test number** 949620173210**Result** ✓ Passed



MOT #1	2012-09-26 11:24
MOT test number	169800072294
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
16 January 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	16 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	GY59HHK
Plate since	2019-09-28
Current registration	GY59HHK
Plate since	2019-09-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-29
Last registration	2023-12-18
Complete history	See info



Registration #1	2009-09-29	26 mi
Registration #2	2012-09-26	26.297 mi
Registration #3	2013-09-27	39.995 mi
Registration #4	2014-09-27	53.725 mi
Registration #5	2015-09-19	65.089 mi
Registration #6	2015-09-19	65.089 mi
Registration #7	2016-08-20	71.998 mi
Registration #8	2016-08-20	71.998 mi
Registration #9	2017-07-17	75.759 mi
Registration #10	2017-07-17	75.759 mi
Registration #11	2017-07-17	75.759 mi
Registration #12	2017-07-17	75.759 mi
Registration #13	2017-07-17	75.759 mi
Registration #14	2017-07-17	75.759 mi
Registration #15	2017-07-17	75.759 mi
Registration #16	2017-07-17	75.759 mi
Registration #17	2017-07-17	75.759 mi
Registration #18	2017-07-17	75.759 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1790 mm
Height	1630 mm
Length	4440 mm
Wheel base	2780 mm
Kerb weight	1525 kg
Max. allowed weight	2125 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number

2ZFU215118