



report date: 2024-03-28

General information

| | |
|---------------------|--|
| Make | CITROEN |
| Model | GRAND C4 PICASSO HDI VTR PLUS EGS PICASSO |
| Colour | Brown |
| Year of manufacture | 2009 |
| Top speed | 112 mph |
| 0 - 60 mph | 13.2 seconds |
| Gearbox | 6 speed Semi-Automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 107 BHP |
| Max. torque | 240 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 44.1 mpg |
| Consumption extra urban | 60.1 mpg |
| Consumption combined | 53.3 mpg |
| CO2 emission | 140 g/km |
| CO2 label | E |





Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2022-09-25 |
| Pictures | 50 |
| Listing price | View report |



source: cargurus.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-08-06 |
| Pictures | 0 |
| Listing price | View report |

source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-06-04 |
| MOT pass rate | 63 % |
| MOT passed | 12 |
| Failed MOT tests | 7 |
| Total advice items | 13 |
| Total items failed | 17 |

| | |
|------------------|---|
| MOT #19 | 2023-06-05 15:10 |
| MOT test number | 151470284891 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-04 |
| Advice | Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) |

| | |
|-------------------------|--|
| MOT #18 | 2023-05-11 16:24 |
| MOT test number | 653337131707 |
| Result | ✗ Failed |
| Fail | Offside Front Service brake excessively binding (1.2.1 (f)) |
| Fail | Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) |
| Fail | Offside Front Position lamp not working (4.2.1 (a) (ii)) |
| Fail | Windscreen washer not working (3.5 (a)) |
| Fail | Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) |
| Pass with rectification | Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) |

| | |
|-----------------|------------------|
| MOT #17 | 2022-09-24 13:49 |
| MOT test number | 462985938677 |
| Result | ✓ Passed |

**MOT #16** 2022-09-24 13:49**MOT test number** 134528956638**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #15** 2021-07-27 08:03**MOT test number** 888700409312**Result** ✓ Passed**MOT #14** 2021-07-26 11:44**MOT test number** 811910805263**Result** ✗ Failed**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #13** 2020-08-15 10:30**MOT test number** 811678486647**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #12** 2020-08-14 14:52**MOT test number** 421984323288**Result** ✗ Failed**Fail** Offside Headlamp aim too low (4.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Outer Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #11** 2019-07-26 11:19**MOT test number** 847148463694**Result** ✓ Passed**MOT #10** 2019-07-24 12:18**MOT test number** 181701440080**Result** ✗ Failed**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #9** 2018-07-30 11:55**MOT test number** 284166857694**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2017-08-16 08:11**MOT test number** 314021589094**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #7 2016-08-17 14:20**MOT test number** 877568041170**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #6 2015-09-14 08:39**MOT test number** 122613187898**Result** ✓ Passed**MOT #5** 2015-09-14 08:39**MOT test number** 276237744699**Result** ✗ Failed

- Pass with rectification** Offside Front coil spring broken (2.4.C.1a)

MOT #4 2014-09-20 09:21**MOT test number** 895913464230**Result** ✓ Passed**MOT #3** 2013-09-14 09:32**MOT test number** 549687453296**Result** ✓ Passed



| | |
|-------------------------|--|
| MOT #2 | 2013-09-14 09:32 |
| MOT test number | 105417353245 |
| Result | ✗ Failed |
| Pass with rectification | Nearside Front position lamp(s) not working (1.1.A.3b) |

| | |
|-----------------|--------------------------------------|
| MOT #1 | 2012-09-12 11:05 |
| MOT test number | 907156352239 |
| Result | ✓ Passed |
| Notice | Play in steering rack inner joint(s) |



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
4 June 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 August |
| Days left | 94 |
| MOT expiry date | 4 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2019-09-29 |
| Current registration | |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 21 |
| First mileage registration | 2009-09-20 |
| Last registration | 2023-06-05 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2009-09-20 | 24 mi |
| Registration #2 | 2012-09-12 | 34.977 mi |
| Registration #3 | 2013-09-14 | 45.438 mi |
| Registration #4 | 2014-09-20 | 60.708 mi |
| Registration #5 | 2015-09-14 | 72.219 mi |
| Registration #6 | 2015-09-14 | 72.219 mi |
| Registration #7 | 2016-08-17 | 83.378 mi |
| Registration #8 | 2017-08-16 | 95.434 mi |
| Registration #9 | 2018-07-30 | 103.622 mi |
| Registration #10 | 2019-07-24 | 110.576 mi |
| Registration #11 | 2019-07-26 | 110.589 mi |
| Registration #12 | 2019-09-20 | 110.597 mi |
| Registration #13 | 2019-09-20 | 110.597 mi |
| Registration #14 | 2019-09-20 | 110.597 mi |
| Registration #15 | 2019-09-20 | 110.597 mi |
| Registration #16 | 2019-09-20 | 110.597 mi |
| Registration #17 | 2019-09-20 | 110.597 mi |
| Registration #18 | 2019-09-20 | 110.597 mi |
| Registration #19 | 2019-09-20 | 110.597 mi |
| Registration #20 | 2019-09-20 | 110.597 mi |
| Registration #21 | 2019-09-20 | 110.597 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 87% |
| Children | 78% |
| Pedestrian | 46% |
| Safety systems | 89% |
| Overall rating | 77% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2100 mm |
| Height | 1680 mm |
| Length | 4470 mm |
| Wheel base | 2728 mm |
| Kerb weight | 1499 kg |
| Max. allowed weight | 2060 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | JBBN0169964 |