



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Black
Year of manufacture	-
Top speed	92 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-05
Pictures	10
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #17	2023-01-26 17:59
MOT test number	631631727026
Result	✓ Passed
Next expiry date	2024-02-09
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #16	2023-01-26 17:59
MOT test number	340278847717
Result	✗ Failed
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2022-02-10 15:13
MOT test number	711821217279
Result	✓ Passed
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #14**

2022-02-08 16:07

MOT test number

999892000066

Result**✗ Failed****Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #13**

2021-04-26 10:29

MOT test number

557045213794

Result**✓ Passed****Advice** Park brake travel slightly high**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #12**

2021-04-20 10:50

MOT test number

726515423047

Result**✗ Failed****Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Electronic power steering not working (2.6 (c))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Park brake travel slightly high**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Front Brakes imbalanced across an axle by more than 50% (1.2.1 (b) (ii))**Fail** Electronic power steering warning lamp indicates a system malfunction (2.6 (a))**MOT #11**

2020-04-21 13:57

MOT test number

305036929906

Result**✓ Passed****MOT #10**

2019-08-10 09:27

MOT test number

700051253179

Result**✓ Passed****Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #9** 2018-04-28 10:37**MOT test number** 755541398191**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit on edges 185/60/14 (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit on edges (4.1.E.1)**Advice** Ecu light on**Advice** Offside Front Tyre worn close to the legal limit on edges (4.1.E.1)**Advice** Rear exhaust section heavily corroded and slight leak of gases**MOT #8** 2017-04-12 12:10**MOT test number** 719657361177**Result** ✓ Passed**MOT #7** 2017-04-11 15:13**MOT test number** 323467566747**Result** ✗ Failed**Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #6** 2016-05-31 15:39**MOT test number** 726623850609**Result** ✓ Passed**Advice** Wiper blades smearing slightly

**MOT #5** 2016-05-27 13:56**MOT test number** 517385468317**Result** ✗ Failed**Advice** Wiper blades smearing slightly**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm 185 60 14 (4.1.E.1)**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm 185 60 14 (4.1.E.1)**MOT #4** 2015-05-30 12:19**MOT test number** 407400155165**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2015-05-29 13:08**MOT test number** 497569145176**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2014-06-20 11:10**MOT test number** 429781574175**Result** ✓ Passed**MOT #1** 2013-06-10 15:09**MOT test number** 317781063103**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 DF10AUJ
Plate since	2019-03-29
Current registration	 DF10AUJ
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-06-30
Last registration	2023-01-26
Complete history	See info



Registration #1	2010-06-30	10 mi
Registration #2	2013-06-10	42.281 mi
Registration #3	2014-06-20	57.051 mi
Registration #4	2015-05-29	68.865 mi
Registration #5	2015-05-30	68.865 mi
Registration #6	2016-05-27	79.335 mi
Registration #7	2016-05-31	79.335 mi
Registration #8	2017-04-11	85.942 mi
Registration #9	2017-04-12	85.942 mi
Registration #10	2018-04-28	96.344 mi
Registration #11	2019-05-29	101.337 mi
Registration #12	2019-05-29	101.337 mi
Registration #13	2019-05-29	101.337 mi
Registration #14	2019-05-29	101.337 mi
Registration #15	2019-05-29	101.337 mi
Registration #16	2019-05-29	101.337 mi
Registration #17	2019-05-29	101.337 mi
Registration #18	2019-05-29	101.337 mi
Registration #19	2019-05-29	101.337 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CHF 062496