



report date: 2024-03-29

## General information

Make	VOLVO
Model	S60 D2 R-DESIGN
Colour	Grey
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-08-19
Pictures	10
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-09-29
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	17
Total items failed	7

MOT #13	2023-09-29 11:43
MOT test number	401005749037
Result	✓ Passed
Next expiry date	2024-09-29

MOT #12	2022-09-21 12:57
MOT test number	260187120285
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))

MOT #11	2021-09-28 16:27
MOT test number	887899562286
Result	✓ Passed
Advice	Nearside Play in steering rack inner joint(s)

**MOT #10**

2021-09-28 09:26

**MOT test number**

990015418742

**Result**

✗ Failed

**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Play in steering rack inner joint(s)**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #9**

2020-09-30 13:02

**MOT test number**

971073554670

**Result**

✓ Passed

**Advice** Offside Front Upper strut bearing notchy**MOT #8**

2020-09-30 11:52

**MOT test number**

393263936671

**Result**

✗ Failed

**Advice** Offside Front Upper strut bearing notchy**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #7** 2019-06-03 09:36**MOT test number** 832046014527**Result** ✓ Passed

- Advice** Offside Rear tyre age cracks and wear mark inner tyre wall
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Outer sill not fully inspected due to covers
- Advice** Underside floor not fully inspected due to covers
- Advice** Offside Front top strut mount bearing possible wear due to spring noise needs further investigating
- Advice** Rear Child Seat fitted not allowing full inspection of adult belt
- Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Offside Outer sill not fully inspected due to covers

**MOT #6** 2018-06-04 09:31**MOT test number** 705208685454**Result** ✓ Passed**MOT #5** 2018-05-31 09:06**MOT test number** 640146590937**Result** ✗ Failed

- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #4** 2017-09-26 11:08**MOT test number** 752563950664**Result** ✓ Passed

- Advice** Front brake pads and discs becoming worn
- Advice** Underbody plastic trim fitted

**MOT #3** 2017-09-26 11:08**MOT test number** 848523865171**Result** ✗ Failed**Pass with rectification** Rear Registration plate lamp does not illuminate simultaneously with the position lamps n/s o/s (1.1.C.1a)**Advice** Front brake pads and discs becoming worn**Advice** Underbody plastic trim fitted**MOT #2** 2016-09-23 08:20**MOT test number** 321809450398**Result** ✓ Passed**MOT #1** 2015-09-23 13:38**MOT test number** 885267079529**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
29 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	29 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 <b>AK62NUP</b>
Plate since	2019-09-29
Current registration	 <b>AK62NUP</b>
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-09-28
Last registration	2023-09-29
Complete history	<a href="#">See info</a>



Registration #1	2012-09-28	23 mi
Registration #2	2015-09-23	49.391 mi
Registration #3	2016-09-23	65.227 mi
Registration #4	2017-09-26	75.831 mi
Registration #5	2017-09-26	75.831 mi
Registration #6	2018-05-31	81.522 mi
Registration #7	2018-06-04	81.525 mi
Registration #8	2019-06-03	91.267 mi
Registration #9	2020-06-03	101.009 mi
Registration #10	2021-06-03	110.751 mi
Registration #11	2022-06-03	120.493 mi
Registration #12	2023-06-03	130.235 mi
Registration #13	2023-09-29	139.977 mi
Registration #14	2023-09-29	139.977 mi
Registration #15	2023-09-29	139.977 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	2259719