



G20FFH

report date: 2024-03-29

General information

|                     |                                    |
|---------------------|------------------------------------|
| Make                | VOLKSWAGEN                         |
| Model               | TRANSPORTER T28 SWB PBV P/V 102TDI |
| Colour              | Red                                |
| Year of manufacture | 2009                               |
| Gearbox             | 5 speed Manual                     |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 101 BHP             |
| Max. torque             | 250 Nm at 2.000 rpm |
| Engine capacity         | 1.896 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 28.0 mpg            |
| Consumption extra urban | 40.9 mpg            |
| Consumption combined    | 40.9 mpg            |



LABEL UNKNOWN



Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-10-03                  |
| Pictures      | 6                           |
| Listing price | <a href="#">View report</a> |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2025-02-28 |
| MOT pass rate      | 73 %       |
| MOT passed         | 11         |
| Failed MOT tests   | 4          |
| Total advice items | 17         |
| Total items failed | 17         |

|                  |   |
|------------------|---|
| MOT #15          | 2024-02-29 17:59  |
| MOT test number  | 274203109598  |
| Result           | ✓ Passed  |
| Next expiry date | 2025-02-28  |
| Minor            | Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i)) |

|                 |   |
|-----------------|---|
| MOT #14         | 2024-02-29 14:03  |
| MOT test number | 583603337561  |
| Result          | ✗ Failed  |
| Fail            | Nearside Headlamp light source and lamp not compatible (4.1.4 (c))  |
| Fail            | Parking brake efficiency below requirements (1.4.2 (a) (i))   |
| Fail            | Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))                                  |
| Fail            | Offside Side repeater not working (4.4.1 (a) (ii))  |
| Fail            | Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))  |
| Fail            | Offside Headlamp light source and lamp not compatible (4.1.4 (c))   |
| Fail            | Offside Stop lamp(s) not working (4.3.1 (a) (ii))   |
| Minor           | Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i)) |
| Fail            | Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))   |

**MOT #13** 2022-11-29 12:48**MOT test number** 520410993452**Result** ✓ Passed**Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** N/s/f outer cv boot weeping**MOT #12** 2021-12-01 14:47**MOT test number** 604771184035**Result** ✓ Passed**MOT #11** 2021-11-17 11:16**MOT test number** 289657795349**Result** ✗ Failed**Fail** Nearside Front Lower Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Minor** Offside Front Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Nearside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Minor** Nearside Front Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #10** 2020-11-14 11:33**MOT test number** 941532975681**Result** ✓ Passed

**MOT #9** 2019-05-16 15:10**MOT test number** 453295184771**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #8** 2017-09-11 15:28**MOT test number** 666868540216**Result** ✓ Passed**Advice** Rear Inner Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2017-09-07 14:20**MOT test number** 946894326241**Result** ✗ Failed**Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)**Fail** Offside Rear Stop lamp not working (1.2.1b)**Advice** Rear Inner Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2016-09-02 15:05**MOT test number** 779904334033**Result** ✓ Passed**MOT #5** 2015-09-11 12:05**MOT test number** 346375652274**Result** ✓ Passed

**MOT #4** 2014-11-21 13:40**MOT test number** 276865724313**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-10-28 11:59**MOT test number** 189951503353**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**Notice** N/s mirror case damaged**Advice** Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #2** 2013-10-28 11:59**MOT test number** 757951003346**Result** ✗ Failed**Notice** N/s mirror case damaged**Advice** Nearside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #1** 2012-11-19 16:10**MOT test number** 236044422360**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 September 2024

✓  
**MOT**

**Expires:**  
28 February 2025

|                  |  |                                 |
|------------------|--|---------------------------------|
| Tax status       |  | Valid until 1 September         |
| Days left        |  | 125                             |
| MOT expiry date  |  | 28 February 2025                |
| Full MOT history |  | <a href="#">See MOT history</a> |



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

|                      |   |
|----------------------|---|
| Number of plates     | 1   |
| Current registration |  <b>G20FFH</b> |
| Plate since          | 2024-03-29  |
| Current registration |  <b>G20FFH</b> |
| Plate since          | 2024-03-29  |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


|                   |             |
|-------------------|-------------|
| Finance company   | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type    | XXXXXXXX XX |
| Agreement term    | XXXXXXXX XX |
| Agreement number  | XXXXXXXX XX |
| Contact info      | XXXXXXXX XX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 16                       |
| First mileage registration | 2009-11-10               |
| Last registration          | 2024-02-29               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2009-11-10 | 6 mi       |
| Registration #2  | 2012-11-19 | 31.440 mi  |
| Registration #3  | 2013-10-28 | 50.487 mi  |
| Registration #4  | 2014-11-21 | 66.582 mi  |
| Registration #5  | 2015-09-11 | 70.158 mi  |
| Registration #6  | 2016-09-02 | 87.908 mi  |
| Registration #7  | 2017-09-07 | 105.226 mi |
| Registration #8  | 2017-09-11 | 105.477 mi |
| Registration #9  | 2018-09-02 | 122.777 mi |
| Registration #10 | 2019-09-02 | 140.077 mi |
| Registration #11 | 2020-09-02 | 157.377 mi |
| Registration #12 | 2021-09-02 | 174.677 mi |
| Registration #13 | 2022-09-02 | 191.977 mi |
| Registration #14 | 2023-09-02 | 209.277 mi |
| Registration #15 | 2024-02-29 | 226.577 mi |
| Registration #16 | 2024-02-29 | 243.877 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1904 mm |
| Height              | 2170 mm |
| Length              | 4890 mm |
| Wheel base          | 3000 mm |
| Kerb weight         | 1817 kg |
| Max. allowed weight | 2800 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 80 l             |
| Fuel delivery      | Direct Injection |
| Number of seats    | 3                |

|                 |            |
|-----------------|------------|
| Number of axles | 2          |
| Engine number   | BRS 152305 |