





General information

Make	RENAULT
Model	CLIO DYNAMIQUE MEDIANAV ENERGY TCE S/S
Colour	Yellow
Year of manufacture	2013
Top speed	113 mph
0 - 60 mph	12.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	135 Nm at 2.500 rpm
Engine capacity	899 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	В





Internet history

Entry 1

Date

2021-03-07

7

Pictures

Listing price

View report



source: yesauto.com



MOT history

MOT expiry date	2025-02-05
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	23
Total items failed	4

MOT #11	2024-02-02 15:04
MOT test number	361019371012
Result	✓ Passed
Next expiry date	2025-02-05
Advice Offside Front Tyre worn close to legal limit/worn on edge *** ON LIMIT (5.2.3 (e))	*** + bald on inner edge
Advice Offside Rear Shock absorbers has light misting of oil *** SIGNIFICANT	*** (5.3.2 (b))
Advice Nearside Front Tyre worn close to legal limit/worn on edge *** ON LIM (5.2.3 (e))	IT *** + bald on inner edge

MOT #10 2024-02-02 15:04 **MOT test number** 881617489558 Result × Failed Advice Offside Rear Shock absorbers has light misting of oil *** SIGNIFICANT *** (5.3.2 (b)) Offside Front Tyre worn close to legal limit/worn on edge *** ON LIMIT *** + bald on inner edge Advice (5.2.3 (e)) Pass with rectification Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) Advice Nearside Front Tyre worn close to legal limit/worn on edge *** ON LIMIT *** + bald on inner edge (5.2.3 (e))



HN63YPG report date: 2024-03-28

MOT #9		2023-02-06 16:13
MOT test	number	310093615105
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8	2022-01-06 16:04
MOT test number	826269998519
Result	✓ Passed

MOT #7		2020-12-21 16:14
MOT test	number	833616741694
Result		✓ Passed
Minor	Offside Windscreen wiper blade defective (3.4 (b) (i))	
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))	

МОТ #6	2020-12-21 15:16	
MOT test number	325384169423	
Result	🗙 Failed	
Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))		
Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))		
Minor Offside Windscreen wiper blade defective (3.4 (b) (i))		



MOT #5

<u></u>) (CAR CHECK	report date: 2024-03-28
MOT #5		2019-12-11 13:21
MOT test	number	318683715934
Result		✓ Passed
Advice	Rear tyres cracking on sidewalls	
Advice	Vehicles internal headlight adjuster altered to recheck lights	

LN62VDC

Advice	Front brake pads worn very low		
Advice	Advice Items removed from driver's view prior to test		
Advice	Advice Front brake discs worn/lipped		
MOT #4		2018-12-08 09:30	
MOT test	MOT test number 414198459168		
Result Versed			
MOT #3		2018-12-08 09:30	
MOT test number 534845459269			
Result		🗙 Failed	

Pass with rectification	Brake pedal anti-slip provision worn smooth (1.1.2 (c))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a))

MOT #2		2017-12-08 08:55
MOT test	number	763591295883
Result		✓ Passed
Advice	Both front tyres wearing on inner edges	
Advice	Both front tyres on 3mm	
Advice	Both front discs lipped	
Advice	Front Brake pad(s) wearing thin worn close to limit (3.5.1g)	





5-12-14 09:31
13322151120
🗸 Passed



Tax & MOT check

✓ Taxe Tax due:	d	Expires:	✓ МОТ
1 April 2025		Expires: 5 February 2025	
Tax status			Valid until 1 April
Days left			337
MOT expiry date			5 February 2025
Full MOT history			See MOT history
Tax calculation			

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4. ARMPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



HN63YPG report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-12-30
Last registration	2024-02-02
Complete history	See info



Registration #1	2013-12-30	19 mi
Registration #2	2016-12-14	25.674 mi
Registration #3	2017-12-08	35.028 mi
Registration #4	2018-12-08	42.388 mi
Registration #5	2018-12-08	42.388 mi
Registration #6	2019-12-11	50.085 mi
Registration #7	2020-12-21	55.685 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.777 mi



HN63YPG report date: 2024-03-28

Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	88%
Children	89%
Pedestrian	66%
Safety systems	99%
Overall rating	85%
Video	see crash video



Dimensions & weight	
Width	1732 mm
Height	1488 mm
Length	4062 mm
Wheel base	2589 mm
Kerb weight	980 kg
Max. allowed weight	1588 kg
Additional information	
Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	U124302