





report date: 2024-03-28

### General information

Make	MINI
Model	PACEMAN COOPER D
Colour	Grey
Year of manufacture	2015
Top speed	115 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	116 g/km
CO2 label	С



CarCheck.co.uk page 1/12



## Internet history

#### Entry 1

Date 2021-07-21

Pictures 24

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-04-25
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	7
Total items failed	6

MOT #10	2024-04-26 14:24
MOT test number	416448750689
Result	✓ Passed
Next expiry date	2025-04-25

MOT #9		2024-04-26 14:24
MOT test number		376935318218
Result		<b>×</b> Failed
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	

MOT #8		2023-04-21 09:37
MOT test	number	672437775956
Result		✓ Passed
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge 225/45/18 rft (5.2.3 (e))		(5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



MOT #7 2022-04-07 14:03

**MOT test number** 184473504754

**Result** ✓ Passed

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #6 2021-04-23 14:04

**MOT test number** 463260428227

**Result** ✓ Passed

MOT #5 2020-09-28 08:00

**MOT test number** 131258445838

MOT #4 2019-10-02 08:29

MOT test number 761594158118

Result 

Passed

MOT #3 2019-10-01 05:51

**MOT test number** 905809189816

**Result** X Failed

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Fail Nearside Side repeater not working (4.4.1 (a) (ii))

MOT #2 2018-10-12 14:33

**MOT test number** 755792242012

**Result** 
✓ Passed

CarCheck.co.uk page 4/12



MOT test number

649467273668

Result

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	25 April 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

, ,		
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report		e?
THE PARTY OF THE P		
***************************************		
HEREEN CO.		
***************************************		
*************		
	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	NK NK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-09-29
Last registration	2024-04-26
Complete history	See info



Registration #1	2015-09-29	9 mi
Registration #2	2018-10-11	27.170 mi
Registration #3	2018-10-12	27.170 mi
Registration #4	2019-10-01	31.285 mi
Registration #5	2019-10-02	31.301 mi
Registration #6	2020-09-28	38.001 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



## Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1310 kg
Max. allowed weight	1820 kg

# Additional information

Fuel tank capacity	47
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles2Engine number73619111