





report date: 2024-03-29

General information

Make	FIAT
Model	500X MULTIJET CROSS
Colour	Bronze
Year of manufacture	2018
Top speed	118 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.956 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.6 mpg
CO2 emission	144 g/km
CO2 label	F



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-10-18

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

NAC	٦Т.	بہا: حا	L
MC	ノレ	nis	tory

MOT expiry date	2024-10-12
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	8
Total items failed	7

MOT #5	2023-10-12 11:39
MOT test number	918748286739
Result	✓ Passed
Next expiry date	2024-10-12
Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #4	2022-10-13 13:46
MOT test number	698168520005
Result	✓ Passed

MOT #3	202	2-08-30 16:18
MOT test	number 2	11423237559
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #2 2022-08-30 15:15 **MOT** test number 877191280438 Result × Failed Fail Offside Front Road wheel fixing missing (5.2.1 (a) (i)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Fail Offside Rear Road wheel fixing missing (5.2.1 (a) (i)) Advice TPMS light on Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) Fail Fail Nearside Front Road wheel fixing missing (5.2.1 (a) (i)) Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Fail Nearside Rear Road wheel fixing missing (5.2.1 (a) (i)) Fail Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) Brake performance not tested Due to front tyre condition (1.2.1 (g)) Fail Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #1	2021-05-22 09:05
MOT test number	953468813140
Result	✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	12 October 2024
Full MOT history	See MOT history

Tax calculation

-	
Vehicle class	49
Band	Н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history	
For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	UK NE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-05-31
Last registration	2023-10-12
Complete history	See info



Registration #1	2018-05-31	29 mi
Registration #2	2021-05-22	22.953 mi
Registration #3		11.777 es
Registration #4	2022-08-30	33.070 mi
Registration #5		11.777 es
Registration #6		71.777 44
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	86%
Children	85%
Pedestrian	74%
Safety systems	64%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	2025 mm
Height	1620 mm
Length	4273 mm
Wheel base	2570 mm
Kerb weight	1495 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	48 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 11/11