





report date: 2024-03-29

General information

Make	RENAULT
Model	SCENIC DYNAMIQUE TOMTOM BOSE PACK DCI
Colour	Blue
Year of manufacture	2011
Top speed	112 mph
0 - 100 km/h	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	78 kW / 106 HP / 110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	128 g/km
CO2 label	D



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 4

Date 2022-01-13

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 3

Date	2021-12-30
------	------------

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date 2021-12-30

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk



report date: 2024-03-29

MOT history

MOT expiry date	2024-11-24
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	20
Total items failed	4


MOT #11		2023-11-20 14:51
MOT test	number	350598905244
Result		✓ Passed
Next expiry date 2024-13		2024-11-24
Advice	Offside Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))	

MOT #10		2022-11-21 12:39
MOT test	number	320410181538
Result		✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c	E))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11	(c))
Advice	Central Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 3/13



report date: 2024-03-29



MOT #8	2021-11-25 13:31
MOT test number	998303282381
Result	✓ Passed
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.1	4 (a) (ii))
Minor Nearside Rear Position lamp with a multiple light source up to 1/2 not func	tioning (4.2.1 (a) (i))
Advice Rear Service brake fluctuating, but not excessively (1.2.1 (e))	

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #7	2021-11-24 14:03
MOT test number	342719707093
Result	× Failed
Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Advice Rear Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))
Minor Nearside Rear Position lamp with a multiple light source up to 1/2 not functi	oning (4.2.1 (a) (i))

Minor Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))		
MOT #6	2019-04-03 09:34	
MOT test number	363795592412	
Result	✓ Passed	
MOT #5	2018-08-30 07:02	
MOT test number	359517297552	
Result	✓ Passed	
MOT #4	2017-08-09 08:34	
MOT test number	298866498297	
Result	✓ Passed	
MOT #3	2016-07-26 07:31	
MOT test number	232451730344	
Result	✓ Passed	
MOT #2	2015-08-17 09:30	
MOT test number	996009341223	
Result	✓ Passed	

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1 2014-09-10 11:00
MOT test number 787143654249

Result ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	24 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

\sim	1001	L :	-+-	100
UV	ner	ш	SIC	ш

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

manus .	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-09-09
Last registration	2023-11-20
Complete history	See info



Registration #1	2011-09-09	6 mi
Registration #2	2014-09-10	25.968 mi
Registration #3	2015-08-17	30.970 mi
Registration #4	2016-07-26	38.295 mi
Registration #5	2017-08-09	55.350 mi
Registration #6	2018-08-30	71.874 mi
Registration #7	2019-04-03	82.403 mi
Registration #8	2021-11-24	97.403 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1486 mm
Height	1637 mm
Length	4344 mm
Wheel base	2703 mm
Kerb weight	1385 kg
Max. allowed weight	1944 kg

Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2

Engine number D246598