





report date: 2024-03-29

General information

| Make | MINI |
|---------------------|----------------|
| Model | MINI COOPER S |
| Colour | Blue |
| Year of manufacture | 2013 |
| Top speed | 142 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 184 BHP |
|-------------------------|---------------------|
| Max. torque | 240 Nm at 1.600 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 38.7 mpg |
| Consumption extra urban | 56.5 mpg |
| Consumption combined | 48.7 mpg |
| CO2 emission | 136 g/km |
| CO2 label | E |



CarCheck.co.uk page 1/12



YX63PTU

report date: 2024-03-29

Internet history

Entry 1

Date 2021-09-10


Pictures 4

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2024-08-01 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 8 |
| Failed MOT tests | 0 |
| Total advice items | 14 |
| Total items failed | 0 |

| MOT #8 | | 2023-07-20 08:35 |
|-----------|---|-----------------------|
| MOT test | number | 235406363260 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-08-01 |
| Advice | Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice | Nearside Rear Brake disc worn, pitted or scored, but not seriously weaker | ned (1.1.14 (a) (ii)) |
| Advice | Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice | Offside Rear Brake disc worn, pitted or scored, but not seriously weakene | d (1.1.14 (a) (ii)) |
| Advice | Offside Rear Nail in tyre | |
| Advice | Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) | |

CarCheck.co.uk page 3/12



MOT #7 2022-07-27 13:29

MOT test number 934308909629

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn to legal limit (5.2.3 (e))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Rear Nail in tyre

Advice Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge worn to legal limit and nail in tread (5.2.3 (e))

Advice Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #6 2021-07-05 11:36

MOT test number 213299246501

Result ✓ Passed

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #5 2020-07-28 10:40

MOT test number 238487090894

MOT #4 2019-07-26 13:41

MOT test number 961334194969

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2018-07-10 14:57

MOT test number 405191325305

Result

Passed

CarCheck.co.uk page 4/12



| MOT #2 | 2017-07-27 09:40 |
|-----------------|------------------|
| MOT test number | 149233547235 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2016-08-02 08:46 |
| MOT test number | 110509557270 |
| Result | ✓ Passed |

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 March |
|------------------|---------------------|
| Days left | 305 |
| MOT expiry date | 1 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | Е |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 6/12



YX63PTU

report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| Owner mistory | | |
|--|-------------|--|
| For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report | | |
| | | |
| | | |
| *************************************** | | |
| | | |
| HEREER PARTY AND ADDRESS OF THE PARTY AND ADDR | | |
| *************************************** | | |
| ************************************** | | |
| | More info > | |
| Plate changes | | |
| See in this check if this MINI had different number plates. | | |
| Number of plates | | |
| Current registration | NK NE | |
| Plate since | | |
| Current registration | OK OK | |
| Plate since | | |
| | More info > | |
| | | |

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



YX63PTU

report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2013-09-28 |
| Last registration | 2023-07-20 |
| Complete history | See info |



| Registration #1 | 2013-09-28 | 27 mi |
|---------------------------------|------------|-------------------------------------|
| Registration #2 | 2016-08-02 | 16.934 mi |
| Registration #3 | 2017-07-27 | 28.461 mi |
| Registration #4 | 2018-07-10 | 40.279 mi |
| Registration #5 | 2019-07-26 | 52.891 mi |
| | | |
| Registration #6 | | 11.777 es |
| | | 11.777 ea 11.777 ea |
| Registration #6 | | 11.77 es 11.77 es |
| Registration #6 Registration #7 | | 11.777 es 11.777 es 11.777 es |

More info >

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 60567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1683 mm |
|---------------------|---------|
| Height | 1407 mm |
| Length | 3714 mm |
| Wheel base | 2467 mm |
| Kerb weight | 1130 kg |
| Max. allowed weight | 1590 kg |

Additional information

| Fuel tank capacity | 50 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| Number of seats CarCheck.co.uk | 4 page 12/1 |

Number of axles2Engine numberA767J575