





report date: 2024-03-29

General information

Make	AUDI
Model	A8 TDI QUATTRO SE
Colour	Blue
Year of manufacture	2007
Top speed	151 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	229 BHP
Max. torque	450 Nm at 1.400 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	23.5 mpg
Consumption extra urban	44.1 mpg
Consumption combined	33.6 mpg
CO2 emission	224 g/km
CO2 label	K



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Entry 1

Date 2021-11-21

Pictures 40

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-08-14
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	20
Total items failed	9

MOT #19	2023-08-03 10:03
MOT test number	712895278698
Result	✓ Passed
Next expiry date	2024-08-14

MOT #18	2022-08-15 11:13
MOT test number	586774137666
Result	✓ Passed

MOT #17	2021-08-04 07:55
MOT test number	619614893210
Result	✓ Passed

MOT #16	2020-08-10 13:42
MOT test number	579502423760
Result	✓ Passed
Advice Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))	

MOT #15	2019-08-12 13:42
MOT test number	724362295709
Result	✓ Passed

CarCheck.co.uk page 3/14



MOT test number

Result

FD57FWO

report date: 2024-03-29

× Failed

MOT #14 2019-08-12 13:42 756605632512

Result × Failed

Pass with rectification Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))

Pass with rectification Nearside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #13 2018-04-23 17:05

MOT test number 568276344537

Result ✓ Passed

MOT #12 2017-05-19 09:30

MOT test number 495112163693

Result Passed

Advice Nearside Rear Tyre worn close to the legal limit 255/40zr19 (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit 255/40zr19 (4.1.E.1)

2016-05-20 13:06 MOT #11

MOT test number 814066022766

Result ✓ Passed

MOT #10 2016-05-20 09:45

MOT test number 436840684050

Offside Front Tyre has ply or cords exposed 255/40/r19 (4.1.D.1b) Fail

Fail Nearside Front Tyre has ply or cords exposed 255/40/r19 (4.1.D.1b)

MOT #9 2015-05-14 09:13

MOT test number 605944035178

Result ✓ Passed

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #8 2015-05-14 09:02

MOT test number 919324635112

Result X Failed

Fail Rear registration plate has a feature which changes the appearance or legibility of the characters (6.3.4c)

Fail Front registration plate has a feature which changes the appearance or legibility of the characters (6.3.4c)

MOT #7 2014-05-20 16:44

MOT test number 265210244156

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

MOT #6 2014-05-20 09:36

MOT test number 909710844132

Result X Failed

Advice Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #5 2014-05-06 10:20

MOT test number 765736424156

Result X Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Offside Front front brake binding (3.7.B.1)

MOT #4 2013-10-01 12:02

MOT test number 399614273428

Result ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice Offside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive

movement (2.4.G.2)

MOT #3 2012-10-13 13:19

MOT test number 576517082207

Result

Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2011-11-03 11:38

MOT test number 629907501362

Result
✓ Passed

CarCheck.co.uk page 6/14



MOT #1

FD57FWO

report date: 2024-03-29

2010-10-14 11:43

MOT test number 361487780235

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	14 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

_	
Owner	history
OWITCE	ilistoi y

For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report	

THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-10-25
Last registration	2023-08-03
Complete history	See info



Registration #1	2007-10-25	28 mi
Registration #2	2010-10-14	35.967 mi
Registration #3	2011-11-03	47.117 mi
Registration #4	2012-10-13	57.826 mi
Registration #5	2013-10-01	67.929 mi
Registration #6	2014-05-06	69.916 mi
Registration #7	2014-05-20	70.523 mi
Registration #8	2014-05-20	70.536 mi
Registration #9	2015-05-14	82.683 mi
Registration #10	2015-05-14	82.683 mi
Registration #11	2016-05-20	96.248 mi
Registration #12		11.117 es
Registration #13		11.177 es
Registration #14		11.117 es
Registration #15		11.177 es
Registration #16		11.117 es
Registration #17		11.177 es
Registration #18		11.117 es
Registration #19		11.177 es
Registration #20		11.117 es
Registration #21		10.777 mg

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2028 mm
Height	1444 mm
Length	5051 mm
Wheel base	2944 mm
Kerb weight	1830 kg
Max. allowed weight	2430 kg

Additional information

Fuel tank capacity	90	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 page 1	.4/14

Number of axles 2

Engine number ASB 044812