



PEUGEOT




report date: 2024-03-28

General information

Make	PEUGEOT
Model	107 URBAN
Colour	Silver
Year of manufacture	2007
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	109 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-02-03
Pictures	10
Listing price	<a href="#">View report</a>



source: autoonline.co.uk



## MOT history

MOT expiry date	2024-10-11
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	29
Total items failed	4

MOT #16	2023-10-05 15:02
MOT test number	698245123273
Result	✓ Passed
Next expiry date	2024-10-11
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #15	2022-10-07 15:13
MOT test number	742064303061
Result	✓ Passed

MOT #14	2021-10-12 16:15
MOT test number	873018040609
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Under side of vehicle corroded
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13**

2020-09-22 14:47

**MOT test number**

448448782830

**Result**

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge on 2.5mm (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge on 2.5mm (5.2.3 (e))
- Advice** Rear axle beam rusty

**MOT #12**

2020-09-22 10:39

**MOT test number**

860641703254

**Result**

✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge on 2.5mm (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear axle beam rusty
- Advice** Offside Front Tyre worn close to legal limit/worn on edge on 2.5mm (5.2.3 (e))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #11**

2019-04-02 10:28

**MOT test number**

292111965444

**Result**

✓ Passed

- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened axle beam (5.3.3 (b) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #10** 2019-04-01 16:23**MOT test number** 460398801058**Result** ✗ Failed

- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Front Headlamp aim too high (4.1.2 (a))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened axle beam (5.3.3 (b) (i))
- Fail** Nearside Front Headlamp aim too high (4.1.2 (a))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #9** 2018-04-25 11:55**MOT test number** 486505511852**Result** ✓ Passed**MOT #8** 2017-06-10 09:33**MOT test number** 648648933867**Result** ✓ Passed**MOT #7** 2016-06-06 11:58**MOT test number** 717850065531**Result** ✓ Passed

**MOT #6** 2015-10-02 09:43**MOT test number** 539197528382**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #5** 2014-10-02 10:23**MOT test number** 306795974404**Result** ✓ Passed**MOT #4** 2013-09-20 10:18**MOT test number** 607773763222**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-10-09 13:00**MOT test number** 298173682286**Result** ✓ Passed**MOT #2** 2011-09-20 11:09**MOT test number** 808623461277**Result** ✓ Passed



MOT #1	2010-09-24 15:52
MOT test number	484627260278
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
11 October 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	11 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-11-23
Last registration	2023-10-05
Complete history	<a href="#">See info</a>



Registration #1	2007-11-23	14 mi
Registration #2	2010-09-24	2.882 mi
Registration #3	2011-09-20	11.164 mi
Registration #4	2012-10-09	22.844 mi
Registration #5	2013-09-20	33.490 mi
Registration #6	2014-10-02	43.843 mi
Registration #7	2015-10-02	55.612 mi
Registration #8	2016-06-06	60.301 mi
Registration #9	2017-06-10	64.397 mi
Registration #10	2018-06-10	65.377 mi
Registration #11	2019-06-10	65.377 mi
Registration #12	2020-06-10	65.377 mi
Registration #13	2021-06-10	65.377 mi
Registration #14	2022-06-10	65.377 mi
Registration #15	2023-06-10	65.377 mi
Registration #16	2024-06-10	65.377 mi
Registration #17	2025-06-10	65.377 mi
Registration #18	2026-06-10	65.377 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	825 kg
Max. allowed weight	1190 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

Engine number

5379325