



report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 E-HDI AIRDREAM DSPORT PLUS
Colour	Red
Year of manufacture	2013
Top speed	118 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	83.1 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A






Internet history

Entry 2


Date	2023-10-14
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-06
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-05
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	27
Total items failed	7

MOT #10	2023-10-06 12:41
MOT test number	437521031408
Result	✓ Passed
Next expiry date	2024-10-05

MOT #9	2023-10-05 13:22
MOT test number	813100719279
Result	✗ Failed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Offside Rear Parking brake inoperative on one side (1.4.1 (a))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #8	2022-09-21 12:21
MOT test number	620033004435
Result	✓ Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #7**

2021-09-20 10:21

MOT test number

937230695835

Result

✓ Passed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Exhaust mounting defective (6.1.2 (a))**MOT #6**

2020-09-25 13:45

MOT test number

471121981271

Result

✓ Passed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #5**

2020-09-25 10:21

MOT test number

948173773483

Result**✗ Failed****Fail**

Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail

Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail

Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail

Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail

Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #4

2019-09-27 07:30

MOT test number

790034802687

Result**✓ Passed****Advice**

Under trays/covers limit inspection

Advice

Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

Advice

Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i))

**MOT #3** 2018-09-21 09:58**MOT test number** 620709234719**Result** ✓ Passed

- Advice** Front tyres worn on inner edges
- Advice** Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i))
- Advice** Under trays/covers limit inspection
- Minor** Front Outer Drive shaft joint constant velocity boot severely deteriorated both sides (6.1.7 (g) (i))

MOT #2 2017-09-18 09:43**MOT test number** 323000795898**Result** ✓ Passed**MOT #1** 2016-08-04 10:27**MOT test number** 240196260426**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
5 October 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	5 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-08-05
Last registration	2023-10-06
Complete history	See info



Registration #1	2013-08-05	6 mi
Registration #2	2016-08-04	19.020 mi
Registration #3	2017-09-18	31.372 mi
Registration #4	2018-09-21	36.091 mi
Registration #5	2019-09-27	36.564 mi
Registration #6	2020-09-25	45.772 mi
Registration #7	2020-09-25	45.772 mi
Registration #8	2020-09-25	45.772 mi
Registration #9	2020-09-25	45.772 mi
Registration #10	2020-09-25	45.772 mi
Registration #11	2020-09-25	45.772 mi
Registration #12	2020-09-25	45.772 mi
Registration #13	2020-09-25	45.772 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1090 kg
Max. allowed weight	1625 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFS0016371