



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SE DSG 7 STR
Colour	Silver
Year of manufacture	-
Top speed	123 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-30
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #16	2021-02-08 13:20
MOT test number	449807251420
Result	✓ Passed
Next expiry date	2022-02-07
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15	2020-01-07 12:50
MOT test number	648003122648
Result	✓ Passed

MOT #14	2020-01-07 12:50
MOT test number	309712866972
Result	✗ Failed
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #13	2019-01-12 11:34
MOT test number	291057703592
Result	✓ Passed
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Child Seat fitted not allowing full inspection of adult belt

MOT #12	2018-01-24 09:30
MOT test number	727366122572
Result	✓ Passed

**MOT #11** 2017-02-04 14:08**MOT test number** 708320286264**Result** ✓ Passed**MOT #10** 2015-06-03 10:26**MOT test number** 878264355196**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2014-06-03 09:31**MOT test number** 509334454173**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)**Notice** Under-trays fitted obscuring some underside components**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2013-05-29 10:28**MOT test number** 578619943103**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2012-05-31 11:17**MOT test number** 215362052178**Result** ✓ Passed

**MOT #6** 2011-06-03 09:57**MOT test number** 258994951411**Result** ✓ Passed**MOT #5** 2010-05-07 14:40**MOT test number** 184167220133**Result** ✓ Passed**MOT #4** 2010-05-07 14:40**MOT test number** 620147620112**Result** ✗ Failed**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2009-05-15 15:55**MOT test number** 290575639125**Result** ✓ Passed**Notice** Seventh seat folded down, unable to check seat belt and buckle**Notice** Sixth seat folded down, unable to check seat belt and buckle

**MOT #2**

2009-05-11 12:06

MOT test number

164941539105

Result**✗ Failed**

- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Centre Rear Seat belt has a cut which has significantly weakened the webbing (5.2.2a)
- Notice** Seventh seat folded down, unable to check seat belt and buckle
- Fail** Offside Front constant velocity joint gaiter split (2.5.C.1a)
- Fail** Offside Rear Direction indicators incorrect colour (1.4.A.2f)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Offside Rear Stop lamp not working (1.2.1b)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Notice** Sixth seat folded down, unable to check seat belt and buckle
- Fail** Nearside Front constant velocity joint gaiter split (2.5.C.1a)
- Fail** Nearside Rear Direction indicators incorrect colour (1.4.A.2f)
- Fail** Nearside Rear coil spring incomplete (2.4.C.1a)
- Fail** Offside Rear position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)

MOT #1

2008-04-07 10:12

MOT test number

501228198022

Result**✓ Passed**

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 FN05TVY
Plate since	2024-03-28
Current registration	 FN05TVY
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2005-04-08
Last registration	2021-02-08
Complete history	See info



Registration #1	2005-04-08	22 mi
Registration #2	2008-04-07	40.631 mi
Registration #3	2009-05-11	53.784 mi
Registration #4	2009-05-15	53.784 mi
Registration #5	2010-05-07	61.783 mi
Registration #6	2011-06-03	66.461 mi
Registration #7	2012-05-31	72.349 mi
Registration #8	2013-05-29	76.620 mi
Registration #9	2014-06-03	81.791 mi
Registration #10	2015-05-20	85.277 mi
Registration #11	2016-05-20	85.277 mi
Registration #12	2017-05-20	85.277 mi
Registration #13	2018-05-20	85.277 mi
Registration #14	2019-05-20	85.277 mi
Registration #15	2020-05-20	85.277 mi
Registration #16	2021-05-20	85.277 mi
Registration #17	2022-05-20	85.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Max. allowed weight	2290 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles

2

Engine number

BKD 271331