



report date: 2024-03-29

General information

Make	FIAT
Model	PANDA TWINAIR S
Colour	Beige
Year of manufacture	2014
Top speed	117 mph
0 - 60 mph	10.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	145 Nm at 2.000 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	80.7 mpg
Consumption combined	67.3 mpg
CO2 emission	99 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-08-27
Pictures	17
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2024-09-22
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	7
Total items failed	3

MOT #9	2023-09-21 16:17
MOT test number	595492274557
Result	✓ Passed
Next expiry date	2024-09-22

MOT #8	2022-09-01 12:12
MOT test number	911962190244
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2021-09-22 15:25
MOT test number	720036020385
Result	✓ Passed

MOT #6	2020-09-23 15:01
MOT test number	920294803023
Result	✓ Passed

**MOT #5** 2020-09-23 14:18**MOT test number** 649410355258**Result** ✗ Failed**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #4** 2019-03-07 12:04**MOT test number** 780806402067**Result** ✓ Passed**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #3** 2018-03-08 11:40**MOT test number** 262199567250**Result** ✓ Passed**MOT #2** 2018-03-08 11:40**MOT test number** 924855407464**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #1** 2017-02-23 11:49**MOT test number** 368182365558**Result** ✓ Passed**Advice** Outer Brake cable has wires broken but is not significantly weakened (3.5.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
22 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	22 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-03-22
Last registration	2023-09-21
Complete history	See info



Registration #1	2014-03-22	21 mi
Registration #2	2017-02-23	35.296 mi
Registration #3	2018-03-08	37.628 mi
Registration #4	2018-03-08	37.628 mi
Registration #5	2019-03-07	39.539 mi
Registration #6	2020-09-23	41.106 mi
Registration #7	2023-09-21	41.106 mi
Registration #8	2023-09-21	41.106 mi
Registration #9	2023-09-21	41.106 mi
Registration #10	2023-09-21	41.106 mi
Registration #11	2023-09-21	41.106 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1380 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	0252746