



M7UNM


report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF GTI PERFORMANCE DSG
Colour	White
Year of manufacture	2016
Top speed	154 mph
0 - 100 km/h	6.4 seconds
0 - 60 mph	6.4 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	169 kW / 230 HP / 227 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.4 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	147 g/km
CO2 label	F










Internet history

Entry 1

Date	2021-06-12
Pictures	7
Listing price	<a href="#">View report</a>



source: autotrader.co.uk





## MOT history

MOT expiry date	2024-05-05
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	15
Total items failed	0

MOT #7 2024-04-27 10:57

MOT test number 160745040036

Result ✗ Failed

**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #6 2023-05-05 09:11

MOT test number 660015177382

Result ✓ Passed

**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #5 2022-05-03 08:11

MOT test number 458025928524

Result ✓ Passed

**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))



**MOT #4** 2021-05-06 14:47**MOT test number** 824179995060**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3** 2020-03-21 10:34**MOT test number** 257702368008**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #2** 2020-03-20 14:16**MOT test number** 226106285048**Result** ✗ Failed**Advice** Nearside Front Outer Tyre slightly damaged Side wall (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**DANGEROUS** Offside Front Outer Tyre has a tear, caused by separation or partial failure of its structure Side wall (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #1** 2019-03-11 12:23**MOT test number** 891918517324**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (ii))





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
5 May 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	5 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-





Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX


More info >





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-03-11
Last registration	2024-04-27
Complete history	<a href="#">See info</a>



Registration #1	2016-03-11	14 mi
Registration #2	2019-03-11	18.273 mi
Registration #3	2020-03-20	25.105 mi
Registration #4	2020-03-21	25.105 mi
Registration #5	2021-05-06	29.080 mi
Registration #6	2022-05-20	35.277 mi
Registration #7	2023-05-20	35.277 mi
Registration #8	2023-05-20	35.277 mi
Registration #9	2024-04-27	35.277 mi

More info >





Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	89%
Pedestrian	65%
Safety systems	71%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1799 mm
Height	1452 mm
Length	4255 mm
Wheel base	2637 mm
Kerb weight	1370 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5



Number of seats	5
Number of axles	2
Engine number	CHHA143843