




General information

Make	VOLKSWAGEN
Model	TOURAN SE TDI
Colour	Grey
Year of manufacture	2012
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 103 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-20
Pictures	17
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2022-06-15
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	31
Total items failed	6

MOT #19 2021-06-16 10:10

MOT test number 505211508102

Result ✓ Passed

Next expiry date 2022-06-15

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #18 2021-06-16 10:10

MOT test number 242461467264

Result ✗ Failed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Pass with rectification** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

**MOT #17**

2020-12-23 12:27

**MOT test number**

945800105235

**Result**

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #16**

2020-07-15 11:59

**MOT test number**

141947501196

**Result**

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #15**

2019-12-24 12:09

**MOT test number**

179760044350

**Result**

✓ Passed

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front wing panel slight damage
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #14**

2019-06-28 15:08

**MOT test number**

139071572520

**Result**

✓ Passed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #13**

2019-02-28 11:11

**MOT test number**

969546304963

**Result**

✓ Passed

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2019-02-28 11:11

**MOT test number**

856691402344

**Result**

✗ Failed

- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))
- Pass with rectification** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2018-06-26 11:40**MOT test number** 536404232881**Result** ✓ Passed**MOT #10** 2017-12-27 14:53**MOT test number** 205163722053**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2017-12-27 14:53**MOT test number** 194434173855**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2017-06-29 09:15**MOT test number** 878734588192**Result** ✓ Passed**MOT #7** 2017-06-01 12:55**MOT test number** 504518268850**Result** ✓ Passed**MOT #6** 2017-06-01 12:55**MOT test number** 948792529238**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)



MOT #5	2016-06-29 11:29
MOT test number	300578586046
Result	✓ Passed
MOT #4	2016-06-06 08:38
MOT test number	644203731545
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
MOT #3	2015-12-07 12:43
MOT test number	807794233197
Result	✓ Passed
MOT #2	2015-07-01 13:50
MOT test number	258342385455
Result	✓ Passed
MOT #1	2015-03-05 12:30
MOT test number	788994065011
Result	✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
31 March 2022

✕  
MOT

Expired:  
15 June 2022

Tax status	Expired at 31 March 2022
Days left	759 days too late
MOT expiry date	15 June 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>AV12KWR</b>
Plate since	2019-06-29
Current registration	<b>AV12KWR</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2012-03-29
Last registration	2021-06-16
Complete history	<a href="#">See info</a>



Registration #1	2012-03-29	28 mi
Registration #2	2015-03-05	18.444 mi
Registration #3	2015-07-01	19.480 mi
Registration #4	2015-12-07	26.931 mi
Registration #5	2016-06-06	41.837 mi
Registration #6	2016-06-29	44.000 mi
Registration #7	2017-06-01	60.887 mi
Registration #8	2017-06-01	60.887 mi
Registration #9	2017-06-29	66.736 mi
Registration #10	2017-12-27	95.517 mi
Registration #11	2017-12-27	95.517 mi
Registration #12	2018-06-29	124.298 mi
Registration #13	2018-06-29	124.298 mi
Registration #14	2018-06-29	124.298 mi
Registration #15	2018-06-29	124.298 mi
Registration #16	2018-06-29	124.298 mi
Registration #17	2018-06-29	124.298 mi
Registration #18	2018-06-29	124.298 mi
Registration #19	2018-06-29	124.298 mi
Registration #20	2018-06-29	124.298 mi
Registration #21	2021-06-16	124.298 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1474 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

**Number of axles**

2

**Engine number**

CAYCK90899