





report date: 2024-03-28

### General information

Make	FORD
Model	KA TITANIUM
Colour	Red
Year of manufacture	2015
Top speed	99 mph
0 - 100 km/h	13.2 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	51 kW / 69 HP / 68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/12



### Internet history

### Entry 2


Date 2021-08-05

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-06-20

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-09-10
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	18
Total items failed	6

MOT #8		2023-09-11 15:02
MOT test	number	283297025907
Result		✓ Passed
Next expir	ry date	2024-09-10
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Tyre worn close to legal limit/worn on edge all 4 (5.2.3 (e))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/12



MOT #7 2023-09-06 10:15

**MOT test number** 351669336750

Result X Failed

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**Advice** Tyre worn close to legal limit/worn on edge all 4 (5.2.3 (e))

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6 2022-06-16 11:49

MOT test number 169886023359

Advice Offside Rear Tyre worn close to legal limit/worn on edge And tracks in tread (5.2.3 (e))

**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge And cracks it tread (5.2.3 (e))

**Advice** Items removed from driver's view prior to test

**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

CarCheck.co.uk page 4/12



MOT #5 2022-06-16 11:49

**MOT test number** 803041177085

Result X Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge And tracks in tread (5.2.3 (e))

**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**Advice** Items removed from driver's view prior to test

Advice Nearside Rear Tyre worn close to legal limit/worn on edge And cracks it tread (5.2.3 (e))

**Pass with rectification** Nearside Headlamp aim too low and too far to the left. (4.1.2 (a))

Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #4 2021-06-23 10:32

**MOT test number** 837437217981

**Result** ✓ Passed

MOT #3 2020-07-28 07:05

**MOT test number** 943280411808

**Result** ✓ Passed

**MOT #2** 2019-05-03 10:31

MOT test number 647136932661

**Result** ✓ Passed

**MOT #1** 2018-05-01 09:23

MOT test number 549235781824


Result 

Passed

CarCheck.co.uk page 5/12



# Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	10 September 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



_	
Owner	history
OWITE	HIISLUHY

*		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is		ave?
***************************************		
***************************************		
********		
***************************************		
	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-05-31
Last registration	2023-09-11
Complete history	See info



Registration #1	2015-05-31	29 mi
Registration #2	2018-05-01	44.657 mi
Registration #3	2019-05-03	58.939 mi
Registration #4	2020-07-28	71.123 mi
Registration #5		11.777 es
Registration #6	2021-06-23	72.140 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		91,777 esi
Registration #10		11.777 es
Registration #11		11.777 es

More info >

CarCheck.co.uk page 11/12



### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	840 kg

# Additional information

Fuel tank capacity	35 l
Number of axles	2
Engine number	1361424

CarCheck.co.uk page 12/12