



UK

BJIIGZZ

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI
Colour	Blue
Year of manufacture	2011
Top speed	104 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	52.3 mpg
Consumption combined	47.9 mpg





Internet history

Entry 1

Date	2021-08-29
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-01
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	33
Total items failed	14

MOT #16	2023-10-02 08:53
MOT test number	396697225753
Result	✓ Passed
Next expiry date	2024-10-01
Minor	Nearside Front Windscreen damaged but not adversely affecting driver's view to center upper (3.2 (a) (i))

MOT #15	2022-09-27 14:45
MOT test number	677803838585
Result	✓ Passed

MOT #14	2022-09-27 14:45
MOT test number	293567881698
Result	✗ Failed
Pass with rectification	Offside Rear Leaf spring fractured (5.3.1 (b) (i))
Pass with rectification	Nearside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

MOT #13	2021-09-09 07:32
MOT test number	677207670697
Result	✓ Passed
Minor	Nearside Front Upper Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #12** 2021-09-07 13:52**MOT test number** 328555324665**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Minor** Nearside Front Upper Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #11** 2020-10-01 09:21**MOT test number** 170638257793**Result** ✓ Passed**MOT #10** 2020-09-26 14:26**MOT test number** 538301445634**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Service brake efficiency below requirements (1.2.2 (a) (i))**MOT #9** 2019-09-26 09:37**MOT test number** 327629217740**Result** ✓ Passed**Advice** Offside Front Shock absorber starting to weep**Advice** Nearside Rear Tyre walls perished**Advice** Rear Brake disc faces corroded and worn

**MOT #8** 2018-09-27 14:45**MOT test number** 921576997317**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge [195/65/r15]91v firestones (5.2.3 (e))**MOT #7** 2017-09-05 08:05**MOT test number** 791815534252**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Rear discs corroded**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**MOT #6** 2017-09-04 16:33**MOT test number** 529230160714**Result** ✗ Failed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit 1.4mm legal tread remaining (4.1.E.1)**Advice** Rear discs corroded**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**MOT #5** 2016-08-11 11:22**MOT test number** 951926962221**Result** ✓ Passed**Advice** Rear offside tyre badly worn and cracking on inner edge**Advice** Front nearside wheel and tyre side wall slight damage

**MOT #4**

2016-07-12 11:38

MOT test number

884190319526

Result**✗ Failed**

Fail Offside Driver's door hinge deteriorated so the door cannot be readily opened or closed door split around lower door hinge (6.2.B.2)

Advice Rear offside tyre badly worn on inside edge and inner side wall cracking

Fail Offside Rear Leaf spring shackle bracket loose (2.4.B.6a)

Fail Front Windscreen washer provides insufficient washer liquid (8.2.3)

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Advice Front nearside damage to wheel and tyre side wall

Fail Nearside Rear Leaf spring shackle bracket loose (2.4.B.6a)

Fail Service brake: efficiency below requirements (3.7.B.7)

Fail Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)

Advice Remove objects out of drivers view

MOT #3

2015-07-18 10:24

MOT test number

488799495144

Result**✓ Passed**

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Notice Nail in nearside front tyre

Notice Vehicle's internal headlight adjuster altered to recheck lights

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Nail in offside rear tyre



MOT #2	2014-08-09 11:50
MOT test number	628831924267
Result	✓ Passed
Notice	Coolant leak
Notice	Front wipers starting to smear
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	Nail in offside rear tyre
Advice	Rear Stop lamp damaged, but still visible from a reasonable distance (1.2.1d)
Notice	Oil leak

MOT #1	2014-05-24 14:12
MOT test number	715584344117
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 September 2024

✓
MOT

Expires:
1 October 2024

Tax status		Valid until 1 September
Days left		124
MOT expiry date		1 October 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2024-03-29
Current registration	 *****
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-05-31
Last registration	2023-10-02
Complete history	See info



Registration #1	2011-05-31	21 mi
Registration #2	2014-05-24	34.287 mi
Registration #3	2014-08-09	36.523 mi
Registration #4	2015-07-18	46.788 mi
Registration #5	2016-07-12	57.263 mi
Registration #6	2016-08-11	57.264 mi
Registration #7	2017-09-04	67.678 mi
Registration #8	2017-09-05	67.682 mi
Registration #9	2018-09-27	85.374 mi
Registration #10	2019-05-29	95.377 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi
Registration #18	2019-05-29	95.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2062 mm
Height	1841 mm
Length	4875 mm
Kerb weight	1560 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	CAY 511109