



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CARAVELLE EXECUTIVE TDI
Colour	Black
Year of manufacture	2010
Top speed	119 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	180 BHP
Max. torque	400 Nm at 1.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.3 mpg
Consumption extra urban	42.2 mpg
Consumption combined	35.8 mpg
CO2 emission	208 g/km
CO2 label	K






Internet history

Entry 2

Date	2022-02-19
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2022-01-21
Pictures	25
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-23
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	23
Total items failed	13

MOT #17	2024-03-22 14:06
MOT test number	492930011913
Result	✓ Passed
Next expiry date	2025-03-23
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #16	2023-03-24 12:19
MOT test number	872788680194
Result	✓ Passed
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15	2022-03-07 12:16
MOT test number	221479961665
Result	✓ Passed
Minor	Front Lower Suspension arm ball joint dust cover severely deteriorated Both (5.3.4 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2021-04-15 11:46
MOT test number	530054307267
Result	✓ Passed

**MOT #13**

2021-03-29 12:44

MOT test number

127397041060

Result**✗ Failed**

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Front Oil leaking excessively from engine (8.4.1 (a) (i))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Rear Cab or chassis has excessive corrosion, seriously affecting its strength within 30cm of a cab mounting outer sill (6.2.2 (d) (i))

MOT #12

2020-01-14 13:26

MOT test number

684874151736

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #11** 2020-01-14 13:26**MOT test number** 533490977609**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**MOT #10** 2019-01-30 15:03**MOT test number** 256643647007**Result** ✓ Passed**MOT #9** 2018-01-22 11:23**MOT test number** 583619224774**Result** ✓ Passed**MOT #8** 2016-12-15 11:05**MOT test number** 323604513946**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Middle and rear silencers deteriorating

**MOT #7** 2016-12-14 11:24**MOT test number** 132034625574**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Middle and rear silencers deteriorating**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2015-12-07 14:25**MOT test number** 543011748405**Result** ✓ Passed**MOT #5** 2015-02-18 09:18**MOT test number** 698069245005**Result** ✓ Passed**Notice** N/s/r tyre worn to limit bald on outer edge**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Notice** Both front tyres worn to limit**MOT #4** 2014-03-25 10:35**MOT test number** 229114784084**Result** ✓ Passed**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #3** 2014-03-10 15:27**MOT test number** 679349064019**Result** ✓ Passed



MOT #2	2013-01-28 15:07
MOT test number	147148823053
Result	✓ Passed

MOT #1	2013-01-28 15:07
MOT test number	145178423489
Result	✗ Failed

Pass with rectification

 Nearside Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
23 March 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	23 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-01-27
Last registration	2024-03-22
Complete history	See info



Registration #1	2010-01-27	10 mi
Registration #2	2013-01-28	57.735 mi
Registration #3	2014-03-10	82.950 mi
Registration #4	2014-03-25	83.928 mi
Registration #5	2015-02-18	98.715 mi
Registration #6	2015-12-07	110.442 mi
Registration #7	2016-12-14	119.096 mi
Registration #8	2016-12-15	119.096 mi
Registration #9	2018-01-22	128.445 mi
Registration #10	2019-01-30	133.578 mi
Registration #11	2019-01-30	133.578 mi
Registration #12	2019-01-30	133.578 mi
Registration #13	2019-01-30	133.578 mi
Registration #14	2019-01-30	133.578 mi
Registration #15	2019-01-30	133.578 mi
Registration #16	2019-01-30	133.578 mi
Registration #17	2019-01-30	133.578 mi
Registration #18	2019-01-30	133.578 mi
Registration #19	2019-01-30	133.578 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1904 mm
Height	1970 mm
Length	4892 mm
Wheel base	3000 mm
Kerb weight	2377 kg
Max. allowed weight	3000 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Number of axles	2
Engine number	CFC 008931