



report date: 2024-03-29

General information

Make	CITROEN
Model	RELAY 35 L3 HDI
Colour	White
Year of manufacture	2012
Top speed	93 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	129 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.4 mpg
Consumption extra urban	37.7 mpg
Consumption combined	32.5 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date 2022-06-26

Pictures 6

Listing price [View report](#)



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-04
MOT pass rate	56 %
MOT passed	10
Failed MOT tests	8
Total advice items	20
Total items failed	18

MOT #182024-04-05 11:36

MOT test number675497603274

Result✓ Passed

Next expiry date2025-04-04

- Advice

Front Tyre worn close to legal limit/worn on edge both tyres worn on edge/close to limit and cracking/perishing (5.2.3 (e))
- Minor

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Driver's door pillar deteriorated but the door can still be readily opened and closed cracking around door catch (6.2.3 (c) (i))
- Minor

Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice

Front passenger door pillar deteriorated but the door can still be readily opened and closed cracking around door catch (6.2.3 (c) (i))

**MOT #17** 2024-02-29 15:31**MOT test number** 583744754575**Result** ✗ Failed**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Front Tyre worn close to legal limit/worn on edge both tyres worn on edge and cracking /perishing (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside side marker lamp not working**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Passenger seat(s) missing at time of test**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Nearside side marker lamp not working**MOT #16** 2022-10-21 15:58**MOT test number** 109510552327**Result** ✓ Passed**MOT #15** 2022-04-25 15:17**MOT test number** 158100840452**Result** ✓ Passed**Advice** Offside Power steering component has slight seepage from a component steering rack area (2.1.5 (a))

**MOT #14**

2022-04-22 12:12

**MOT test number**

989240209407

**Result****✗ Failed**

- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
- Fail** Offside Headlamp aim too low (4.1.2 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Rear Direction indicator not working (4.4.1 (a) (ii))
- Advice** Offside Power steering component has slight seepage from a component steering rack area (2.1.5 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13**

2021-04-19 12:20

**MOT test number**

996482412065

**Result****✓ Passed**

- Advice** Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12**

2021-04-14 11:15

**MOT test number**

207733339678

**Result****✗ Failed**

- Advice** Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Central Brake pivot has restricted free movement (1.1.15 (e))

**MOT #11**

2020-06-03 14:33

**MOT test number**

300022192795

**Result****✓ Passed**

**MOT #10** 2020-05-15 09:54**MOT test number** 992067386646**Result** ✗ Failed

- Fail** Windscreen washer not working (3.5 (a))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**MOT #9** 2019-05-13 09:00**MOT test number** 677952167514**Result** ✓ Passed**MOT #8** 2019-05-07 09:21**MOT test number** 700924660190**Result** ✗ Failed

- Fail** Offside Rear Seat belt buckle not functioning as intended 2nd buckle from right not fastening (7.1.2 (d))

**MOT #7** 2018-05-03 10:39**MOT test number** 220480919946**Result** ✓ Passed**MOT #6** 2018-04-30 11:25**MOT test number** 754157096198**Result** ✗ Failed

- Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Nearside Rear position lamp(s) not working x2 (1.1.A.3b)
- Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Windscreen wiper does not clear the windscreen effectively both (8.2.2)

**MOT #5** 2017-05-02 16:52**MOT test number** 338180050642**Result** ✓ Passed**MOT #4** 2017-05-02 16:52**MOT test number** 692706757085**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2016-04-28 09:11**MOT test number** 956044654487**Result** ✓ Passed**Advice** Centre rear seat belt stalk cover damaged.**MOT #2** 2016-04-28 08:54**MOT test number** 364383099577**Result** ✗ Failed**Advice** Centre rear seat belt stalk cover damaged.**Fail** Service brake: efficiency below requirements (3.7.B.7)**MOT #1** 2015-04-24 15:31**MOT test number** 749104415146**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 October 2024

✓  
**MOT**

**Expires:**  
4 April 2025

Tax status		Valid until 1 October
Days left		155
MOT expiry date		4 April 2025
Full MOT history		<a href="#">See MOT history</a>





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2012-05-03
Last registration	2024-04-05
Complete history	<a href="#">See info</a>



Registration #1	2012-05-03	19 mi
Registration #2	2015-04-24	8.469 mi
Registration #3	2016-04-28	11.736 mi
Registration #4	2016-04-28	11.736 mi
Registration #5	2017-05-02	13.660 mi
Registration #6	2017-05-02	13.660 mi
Registration #7	2018-04-30	17.154 mi
Registration #8	2018-05-03	17.154 mi
Registration #9	2019-05-07	20.433 mi
Registration #10	2019-05-13	20.433 mi
Registration #11	2019-05-13	20.433 mi
Registration #12	2019-05-13	20.433 mi
Registration #13	2019-05-13	20.433 mi
Registration #14	2019-05-13	20.433 mi
Registration #15	2019-05-13	20.433 mi
Registration #16	2019-05-13	20.433 mi
Registration #17	2019-05-13	20.433 mi
Registration #18	2019-05-13	20.433 mi
Registration #19	2019-05-13	20.433 mi
Registration #20	2019-05-13	20.433 mi

More info >



Dimensions & weight

Width	2350 mm
Height	3500 mm
Length	7383 mm
Wheel base	4035 mm
Kerb weight	1885 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of seats	7
Number of axles	2
Engine number	4H030544252